

(08/11/13) wef

ASS. REC. BY: Jane

REF:

2006

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLM 9015Mat Workshop m/s Borneo Motorof 2, Pramban Crescent

Insured:

LPC

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

71K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLM 9015M

Yr Regn:

2011 / APRType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA PRIUS HYBRID 1.8 CVT c.c. 1798

Colour

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

455714

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3FU503555264

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

29/07/21

Survey held at

BORNEO MOTOR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair Int - 36K

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

): S + RS, SI☐

: Interview (\$

): Photos

☐

: Tech. Invs (\$

): Others

☐

: Weekend (\$

):

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

hncap
 Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	S1000007 / ICLP11	Bodyshop Retail Cash Sales Pandan TCBC Toyota Bodyshop Retail Cash Sales Pandan TCBC Toyota
	Document No. 0	
	Document Date 29/07/2021	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q3	17/04/2017	SLM9015M	0	63657	73/DS/SLM9015M
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDKB3FU503555264	2ZRS034797	60	Ary Chua	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE:28/07/2021 ACC DATE:28/07/2021@12.05PM TP VEH:XE2148J DRIVE IN:28/07/2021 TP Insurer: LONPAC Ins. DATE SURVEY:Rasul(LKKAUTO)29/07/2021@14.14pm NO OF REPAIR DAYS: 14 DAYS				30.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT) FOR REAR RH DOOR				60.00
3	B	BP-LAB2 TO CHECK WIRING AND LIGHTING. TO WATER TEST FOR LEAK.				122.40
4	B	BP-LAB2 TO TRANSFER RHR DOOR GLASS,BOARD ,MECHANISM TO NEW PANEL.				360.00
5	B	BP-LAB2 TO REPLACE REAR RH SIDE ACCIDENT DAMAGE PARTS.STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS. @120 x 5				3600 4320.00
6	B	BP-RES2 TO SPRAY PAINT ON REAR RH SIDE ACCIDENT AFFECTED AREAS. @520 x 4				2360 3540.00
7	1	U81551-47283 LENS & BODY, RR cm	1.00	456.50		456.50
8	2	U81581-47011 LENS & BODY, RR X	1.00	506.70		506.70
9	3	U52159-47913 COVER, RR BUMPER de	1.00	447.20		447.20
10	4	U52453-47010 GUARD, RR BUMPER, cm	1.00	582.20		582.20

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details				
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia		S1000007 / ICLPI1	Bodyshop Retail Cash Sales Pandan TCBC Toyota				
		Document No. 0	Bodyshop Retail Cash Sales Pandan TCBC Toyota				
		Document Date 29/07/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q3	17/04/2017	SLM9015M	0	63657	73/DS/SLM9015M
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDK3FU503555264	2ZRS034797	60	Ary Chua	--/--/----	0.00	--/--/----	0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
11	5	U52161-16010 PIECE, RR BUMPER <i>new</i>	10.00	4.50		45.00	
12	6	U52565-47900 FILLER, RR BUMPER <i>cm</i>	1.00	124.90		124.90	
13	7	U52575-47040 RETAINER, RR BUMPER <i>cm</i>	1.00	118.90		118.90	
14	8	U52576-47040 RETAINER, RR BUMPER <i>X</i>	1.00	117.70		117.70	
15	9	U52023-47030 REINFORCEMENT <i>X</i>	1.00	336.30		336.30	
16	0	U61601-47150 PANEL SUB-ASSY, <i>left 26t</i>	1.00	881.80		881.80	
17	1	U61621-47050 TROUGH, BACK DOOR <i>left</i>	1.00	104.60		104.60	
18	2	T08826-08115 PANEL BONDING AD <i>?</i>	1.00	267.20		267.20	
19	3	U62940-47010 DUCT ASSY, QUARTER <i>?</i>	1.00	67.50		67.50	
20	4	U62505-47011 COVER SUB-ASSY, <i>?</i>	1.00	209.10		209.10	
21	5	U75763-47010 MOULDING, RR DOOR <i>new</i>	1.00	93.20		93.20	
22	6	U75730-47040 MOULDING ASSY, RR <i>new</i>	1.00	114.70		114.70	
23	7	U75765-47010 MOULDING, RR DOOR <i>new</i>	1.00	39.00		39.00	
24	8	U67003-47211 PANEL SUB-ASSY, RR <i>bin</i>	1.00	1306.50		1306.50	
25	9	U75977-47080 STRIPE, RR DOOR, <i>new</i>	1.00	22.10		22.10	
26	0	U75987-47060 STRIPE, RR DOOR, <i>new</i>	1.00	35.30		35.30	
27	1	U75979-47070 STRIPE, RR DOOR, <i>new</i>	1.00	15.50		15.50	
28	2	U69050-52250 LOCK ASSY, RR DOOR <i>?</i>	1.00	567.30		567.30	
29	3	U69803-47020 REGULATOR SUB-ASSY <i>?</i>	1.00	208.40		208.40	
30	4	U85720-47150 MOTOR ASSY, POWER <i>?</i>	1.00	932.80		932.80	
For & on behalf of		Customer's Signature	Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle _____	Parts		Less Amount Due		
			Labour				
			Sublet				
			Lubrication/Fluid				
			Others				

Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia			Account No. S1000007 / ICLPI1		Customer Details Bodyshop Retail Cash Sales Pandan TCBC Toyota Bodyshop Retail Cash Sales Pandan TCBC Toyota		
			Document No. 0				
			Document Date 29/07/2021				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q3	17/04/2017	SLM9015M	0	63657	73/DS/SLM9015M
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDKB3FU503555264	2ZRS034797	60	Ary Chua	--/--/----	0.00	--/--/----	0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
31	5	L90269-04051 RIVET <i>ma</i>	1.00	1.50		1.50	
<u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____			<i> Rasul Hp 90060068 9 days 29/07/21 @ 1430 Reg before paint rasul@lkkauto.com </i>				
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature Please acknowledge receipt of vehicle		Charge Summary Parts 7,601.90 Labour 8,432.40 Sublet 0.00 Lubrication/Fluid 0.00 Others 0.00		Total 16,034.30 GST 7.00% 1,122.40 Less 0.00 Amount Due 17,156.70

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	200G
Vehicle No.:	SLM9015M
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Jul 2021
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	2ZR5034797
Chassis No.:	JTDKB3FU503555264
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	17 Apr 2017
First Registration Date:	17 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Apr 2027
PARF Rebate Amount:	\$3,750.00
COE Expiry Date:	16 Apr 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$54,000.00
COE Rebate Amount:	\$30,854.00
Total Rebate Amount:	\$34,604.00

The information contained herein is correct as at 30 Jul 2021

OK

Toyota Prius Hybrid 1.8A

[Overview](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

Price	\$73,800		
Depreciation [?]	\$12,180 /yr View models with similar depre	Reg Date	07-Jun-2017 (5yrs 10mths 7days COE left)
Mileage	43,000 km (10.4k /yr)	Manufactured [?]	2017
Road Tax [?]	\$976 /yr	Transmission	Auto
Dereg Value [?]	\$34,842 as of today (change)	Fuel Type	Petrol-Electric
COE [?]	\$53,106	OMV [?]	\$29,007
Engine Cap	1,798 cc	ARF [?]	\$5,000
Curb Weight [?]	1,375 kg	Power	90.0 kW (120 bhp)