

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0613/2021/ZK  
**DATE** : 28-Jul-21  
**WIP** : 37208

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 30/07/21**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

**Hi Guo Qiang**  
**4 days - ok - Johnny Boo**  
**4-Oct-21**

**OWNER'S NAME** : MR. TADOKORO DAI  
**ADDRESS** : 119 EMERALD HILL ROAD  
#11-02  
SINGAPORE 229401  
**TELEPHONE** : HP +65 90177328  
**TYPE OF CLAIM** :  
**POLICY NO** : 7210063244  
**VEHICLE NO** : **SNA 5120 H**  
**MODEL CODE** : Q3 SPORTBACK 1.4 TFSI S TRONIC  
**MODEL YEAR** : 25/6/2021  
**ENGINE NO** : CZD C38056  
**CHASSIS NO** : WAUZZZF37M1107305  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 27-Jul-21  
**PLACE OF ACCIDENT** : YORK HOTEL CARPARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

### ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 5120 H

| S/N                         | NATURE OF JOBS                                                                                                                                   |          | ESTIMATED<br>CHARGES | SURVEYOR'S<br>RECOMMENDATIONS |
|-----------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------|----------|----------------------|-------------------------------|
| 1                           | TO REMOVE , CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS,OUTSIDE REMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID. | S/N \$   | 480.00               | \$ <b>480.00</b>              |
| 2                           | TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UIT AND POWER MODULE.                                                                             | S/N \$   | 400.00               |                               |
| 3                           | TO DISMANTLE AND RENEW FRONT BUMPER,RHS FRONT FENDER AND RHS HEADLIGHT.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.      | \$       | 2,400.00             | \$ <b>1,000.00</b>            |
| 4                           | TO RESPRAY FRONT BUMPER,FRONT BUMPER LOWER SPOILER,RHS FRONT FENDER AND BOTH FRONT WHEEL ARCH TRIMS.                                             | \$       | 4,000.00             | \$ <b>1,650.00</b>            |
| 5                           | TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.                                                                                            | S/N \$   | 280.00               |                               |
| 6                           | TO CARRY OUT DIAGNOSTIC CHECK                                                                                                                    | S/N \$   | 192.00               | \$ <b>192.00</b>              |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                  | <b>:</b> | <b>\$ 7,752.00</b>   | <b>\$ 3,322.00</b>            |

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 5120 H**

|                             |                                            |            | <b>DAMAGED PARTS &amp; PRICES</b> |                |                 |
|-----------------------------|--------------------------------------------|------------|-----------------------------------|----------------|-----------------|
| <b>S/N</b>                  | <b>PARTS DESCRIPTION</b>                   | <b>QTY</b> | <b>S/NETT</b>                     | <b>REMARKS</b> |                 |
| 1                           | FRONT BUMPER                               | 1          | \$ 1,335.00                       | \$             | <b>1,068.00</b> |
| 2                           | FRONT BUMPER FIXING PARTS                  | 1          | \$ 414.00                         |                |                 |
| 3                           | FRONT BUMPER UPPER CLOSING ELEMENT - RH    | 1          | \$ 59.00                          |                |                 |
| 4                           | FRONT BUMPER LOWER CLOSING ELEMENT         | 1          | \$ 190.00                         |                |                 |
| 5                           | FRONT BUMPER SPOLIER                       | 1          | \$ 763.00                         | \$             | <b>610.00</b>   |
| 6                           | FRONT BUMPER AIR GUIDE GRILLE - RH         | 1          | \$ 153.00                         |                |                 |
| 7                           | FRONT BUMPER TRIM -RH                      | 1          | \$ 164.00                         |                |                 |
| 8                           | FRONT PARKING SENSOR SUPPORT - RH          | 1          | \$ 25.00                          |                |                 |
| 9                           | FRONT BUMPER GUIDE SECTION - RH            | 1          | \$ 39.00                          |                |                 |
| 10                          | FRONT FENDER - RH                          | 1          | \$ 1,286.00                       | \$             | <b>1,028.80</b> |
| 11                          | FRONT FENDER ATTACHMENT PART               | 1          | \$ 63.00                          |                |                 |
| 12                          | FRONT FENDER BRACE - RH                    | 1          | \$ 88.00                          |                |                 |
| 13                          | FRONT FENDER BRACKET - RH                  | 1          | \$ 32.00                          |                |                 |
| 14                          | FRONT WHEEL HOUSING LINER                  | 1          | TBC                               |                |                 |
| 15                          | FRONT WHEEL HOUSING LINER ATTACHEMENT PART | 1          | \$ 101.00                         |                |                 |
| 16                          | HEADLIGHT - RH                             | 1          | \$ 5,589.00                       |                |                 |
| 17                          | HEADLIGHT LIFT CYLINDER -RH                | 1          | \$ 210.00                         |                |                 |
| 18                          | FRONT WHEEL ARCH COVER LH / RH             | 2          | \$ 1,072.00                       | \$             | <b>857.60</b>   |
| 19                          | FRONT ALUMINIUM RIM - RH                   | 1          |                                   |                |                 |
| 20                          | SUNDRIES                                   | 1          | \$ 350.00                         |                |                 |
| <b>TOTAL SPARE PARTS</b>    |                                            |            | <b>\$ 11,933.00</b>               | <b>\$</b>      | <b>3,564.40</b> |
| <b>TOTAL LABOUR CHARGES</b> |                                            |            | <b>\$ 7,752.00</b>                | <b>\$</b>      | <b>3,322.00</b> |
| <b>GRAND TOTAL</b>          |                                            |            | <b>\$ 19,685.00</b>               | <b>\$</b>      | <b>6,886.40</b> |

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.  
 bl-29/09/21

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**NAME** :  
**SURVEYED DATE** :  
**AUTHORISED DATE** :  
**EXCESS COST** :  
**LIABILITY** :  
**REMARKS** :

**PLEASE NOTE** : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT