

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0613/2021/ZK
DATE : 28-Jul-21
WIP : 37208

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 30/07/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. TADOKORO DAI
ADDRESS : 119 EMERALD HILL ROAD
#11-02
SINGAPORE 229401
TELEPHONE : HP +65 90177328
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210063244
VEHICLE NO : **SNA 5120 H**
MODEL CODE : Q3 SPORTBACK 1.4 TFSI S TRONIC
MODEL YEAR : 25/6/2021
ENGINE NO : CZD C38056
CHASSIS NO : WAUZZZF37M1107305
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 27-Jul-21
PLACE OF ACCIDENT : YORK HOTEL CARPARK



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 5120 H

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE , CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	/
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	?
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,400.00	1000
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, RHS FRONT FENDER AND BOTH FRONT WHEEL ARCH TRIMS.	\$ 4,000.00	1650
5	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	X NA.
6	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00	/
TOTAL LABOUR CHARGES		: \$ 7,752.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 5120 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>/ cut</i>	1	\$ 1,335.00	
2	FRONT BUMPER FIXING PARTS <i>X NN</i>	1	\$ 414.00	
3	FRONT BUMPER UPPER CLOSING ELEMENT - RH <i>?</i>	1	\$ 59.00	
4	FRONT BUMPER LOWER CLOSING ELEMENT <i>X NN</i>	1	\$ 190.00	
5	FRONT BUMPER SPOILER <i>/ cut</i>	1	\$ 763.00	
6	FRONT BUMPER AIR GUIDE GRILLE - RH <i>X NN</i>	1	\$ 153.00	
7	FRONT BUMPER TRIM - RH <i>?</i>	1	\$ 164.00	
8	FRONT PARKING SENSOR SUPPORT - RH <i>?</i>	1	\$ 25.00	
9	FRONT BUMPER GUIDE SECTION - RH <i>?</i>	1	\$ 39.00	
10	FRONT FENDER - RH <i>/ Blue</i>	1	\$ 1,286.00	
11	FRONT FENDER ATTACHMENT PART <i>?</i>	1	\$ 63.00	
12	FRONT FENDER BRACE - RH <i>?</i>	1	\$ 88.00	
13	FRONT FENDER BRACKET - RH <i>?</i>	1	\$ 32.00	
14	FRONT WHEEL HOUSING LINER <i>X NN</i>	1	TBC	
15	FRONT WHEEL HOUSING LINER ATTACHEMENT PART <i>?</i>	1	\$ 101.00	
16	HEADLIGHT - RH <i>?</i>	1	\$ 5,589.00	
17	HEADLIGHT LIFT CYLINDER - RH <i>?</i>	1	\$ 210.00	
18	FRONT WHEEL ARCH COVER LH / RH <i>/ MC</i>	2	\$ 1,072.00	
19	FRONT ALUMINIUM RIM - RH <i>X NN</i>	1	\$ 1,262.00	
20	SUNDRIES <i>?</i>	1	\$ 350.00	
TOTAL SPARE PARTS		:	\$ 13,195.00	
TOTAL LABOUR CHARGES		:	\$ 7,752.00	
GRAND TOTAL		:	\$ 20,947.00	

LEGEND: R/ MARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

Amo Q:af
20/7/21
Excess: TBA
Not Authorised.

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

before paint photos.

4 Days.

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: