

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: LIM.512972.Q Date: 09th Nov 2021

Our Ref: CS1/LAW21008104/Gqf3e2

M/s Riaz LLC

133 New Bridge Road #09-09 Chinatown Point Singapore 059413

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: FBE 1977A INSURED VEHICLE: SJD 5768X

ACCIDENT DATE: 17/08/2018

We thank you for your instruction on 30/07/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FBE 1977A from M/s Advanced Automotive Consultancy Pte Ltd.
- b) Survey report by AJAX Inspection Services Pte Ltd with colour photographs.
- c) Singapore Accident Statement and Police Report of Vehicles FBE 1977A and SJD 5768X.
- d) Colour damaged vehicle photographs of FBE 1977A.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : FBE 1977A

Make & Model : Honda CB400SF H.V.

Chassis Number : NC391021008

Year of Registration : 2001 Engine Capacity : 399 cc

- 2. We recommend that the repairs of the entire damage require about <u>6 (Six)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.