

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21008118/UQCE2

Date: 29/09/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00068942103
Claimant Vehicle No : SJJ6766M **Insured Vehicle No :** GBH5624B
Date of Loss: 30/07/2021 Nature of Claim: TP Claim No: SNM21D204252/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJJ6766M**
Make & Model: HYUNDAI AVANTE, 1.6 (A) Engine No: G4FC9U798966
Reg. Date: 05/02/2010 (Man. Year: 2009) Chassis No: KMH DU41BMAU963523
Colour: White Odometer: 200238 km
Engine Capacity: 1591 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,670.00	1,172.00	498.00	29.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	935.07	590.38	344.69	36.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,605.07	1,762.38	842.69	32.35
Approved Total (Overridden) (S\$)		1,750.00		
(S\$)	2,605.07	1,750.00	855.07	32.82
+ GST 7.00/7.00% (S\$)	182.35	122.50	59.85	32.82
Nett Amount (S\$)	2,787.42	1,872.50	914.92	32.82

INSPECTION

Date of Assignment: 02/08/2021 Present Location: Jin Auto Services Pte Ltd (Defu)
Date Inspected: 02/08/2021 Inspected At: Jin Auto Services Pte Ltd (Defu)
Estimated Period of Repair: 3.0 days Blk 14 Defu Lane 10, #01-410/412
Singapore 539195

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Sep 2021)
Parts:	143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJJ6766M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOTAL PARTS		1,670.00 F	*1,340.00 FL
2	1		*SUNDRY	Necessary	-	*100.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					1,670.00	1,440.00
- List Item Discount on L Items 0.00/20.00% (S\$)					0.00	268.00
Total Parts (S\$)					1,670.00	1,172.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOTAL LABOUR	New	394.80	277.20
2	TOTAL PAINT	New	540.27	313.18
Gross Labour Cost (S\$)			935.07	590.38

Report was unsubmitted during this print-out.

< END OF ESTIMATES >