

Elaine (LKK Auto)

To: WONG JOSEPHINE
Cc: Hui Zhen (LKK Auto); 'SUR'; 'Huey Yon (LKKAuto)'
Subject: RE: Pre-Repair Inspection for SLN 4981 B // Accident on 31/07/2021 @ 16:15HR at along Junction of Stevens Road & Draycott Drive involving Vehicle Number SLN 4981 B & SKA 9001 C Our ref: M12D16292108
Attachments: GIA Rpt.pdf; LKKAdjustment.pdf; LKKInspection.pdf; LKKPhoto.pdf; Resurvey Photo-1.pdf; Resurvey Photo-2.pdf; UOI2-LKKInvoice-AC2106838.pdf

Dear Josephine,

Enclose Survey Report of SLN 4981B.

Thank you.

Best Regards,

Elaine | Reports
LKK Auto Consultants Pte.Ltd.
Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: report@lkkauto.com
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hui Zhen (LKK Auto) [mailto:huizhen@lkkauto.com]
Sent: Friday, 1 October 2021 2:29 PM
To: WONG JOSEPHINE; SUR; Reports (LKKAuto)
Subject: RE: Pre-Repair Inspection for SLN 4981 B // Accident on 31/07/2021 @ 16:15HR at along Junction of Stevens Road & Draycott Drive involving Vehicle Number SLN 4981 B & SKA 9001 C Our ref: M12D16292108

Dear Josephine,

We are in the midst of preparing the report.
Once complete, we will send you a soft copy of survey report.

Dear Reports Team,
Kindly expedite.

Best Regards,

Hui Zhen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: huizhen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: WONG JOSEPHINE [<mailto:josephinewong@uoi.com.sg>]

Sent: Friday, 1 October 2021 10:46 AM

To: Hui Zhen (LKK Auto); SUR

Subject: FW: Pre-Repair Inspection for SLN 4981 B // Accident on 31/07/2021 @ 16:15HR at along Junction of Stevens Road & Draycott Drive involving Vehicle Number SLN 4981 B & SKA 9001 C Our ref: M12D16292108

Without Prejudice

Hi Hui Zhen

Possible to forward me soft copy of survey report as I am wfh and have received third party's claim .

Thanks

Notice

Due to the COVID-19 situation, most of our staff are working from home. While we remain committed to serving you, there may be delay in our customer services. We thank you for your kind understanding under such challenging circumstances.

Josephine Wong

Executive
Claims



United Overseas Insurance Limited

146 Robinson Road, #02-01, UOI Building, Singapore 068909

Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3872 | Email • josephinewong@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

From: Hui Zhen (LKK Auto) <huizhen@lkkauto.com>

Sent: Tuesday, September 28, 2021 1:41 PM

To: WONG JOSEPHINE <josephinewong@uoi.com.sg>; SUR <sur@lkkauto.com>

Cc: LEE KATIE <katielee@uoi.com.sg>

Subject: RE: Pre-Repair Inspection for SLN 4981 B // Accident on 31/07/2021 @ 16:15HR at along Junction of Stevens Road & Draycott Drive involving Vehicle Number SLN 4981 B & SKA 9001 C

CAUTION: This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Dear Josephine,

Kindly provide claim number.

Best Regards,

Hui Zhen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: huizhen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Monday, 2 August 2021 3:16 PM

To: 'WONG JOSEPHINE'; SUR; assignments

Cc: 'LEE KATIE'

Subject: RE: Pre-Repair Inspection for SLN 4981 B // Accident on 31/07/2021 @ 16:15HR at along Junction of Stevens Road & Draycott Drive involving Vehicle Number SLN 4981 B & SKA 9001 C

Dear Sir / Mdm,

Thank you for your assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.

From: WONG JOSEPHINE <josephinewong@uoi.com.sg>

Sent: Monday, 2 August, 2021 3:06 PM

To: SUR <sur@lkkauto.com>; 'assignments' <assignments@lkkauto.com>

Cc: zoomautowerks@gmail.com; LEE KATIE <katielee@uoi.com.sg>

Subject: FW: Pre-Repair Inspection for SLN 4981 B // Accident on 31/07/2021 @ 16:15HR at along Junction of Stevens Road & Draycott Drive involving Vehicle Number SLN 4981 B & SKA 9001 C

Without Prejudice

Dear LKK

Kindly assist to survey third party's vehicle .

Details of survey as email below . Thanks

[Notice](#)

Due to the COVID-19 situation, most of our staff are working from home. While we remain committed to serving you, there may be delay in our customer services. We thank you for your kind understanding under such challenging circumstances.

Josephine Wong

Executive
Claims



United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909

Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3869 | Email • josephinewong@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

From: Zoom Autowerks <zoomautowerks@gmail.com>

Sent: Monday, August 2, 2021 1:00 PM

To: WONG JOSEPHINE <josephinewong@uoi.com.sg>

Cc: LEE KATIE <katielee@uoi.com.sg>

Subject: Re: Pre-Repair Inspection for SLN 4981 B // Accident on 31/07/2021 @ 16:15HR at along Junction of Stevens Road & Draycott Drive involving Vehicle Number SLN 4981 B & SKA 9001 C

CAUTION: This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Dear All,

Please arrange for LKK.

On Mon, Aug 2, 2021, 10:03 WONG JOSEPHINE <josephinewong@uoi.com.sg> wrote:

Without Prejudice

Dear Elin

We propose Autoprobe Consultants , if you do not agree, kindly choose from our lists of surveyors.

[Notice](#)

Due to the COVID-19 situation, most of our staff are working from home. While we remain committed to serving you, there may be delay in our customer services. We thank you for your kind understanding under such challenging circumstances.

Josephine Wong

Executive

Claims



United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909

Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3869 | Email • josephinewong@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

From: Zoom Autowerks <zoomautowerks@gmail.com>

Sent: Monday, August 2, 2021 12:02 AM

To: WONG JOSEPHINE <josephinewong@uoi.com.sg>; LEE KATIE <katielee@uoi.com.sg>

Cc: LEE KATIE <katielee@uoi.com.sg>

Subject: Pre-Repair Inspection for SLN 4981 B // Accident on 31/07/2021 @ 16:15HR at along Junction of Stevens Road & Draycott Drive involving Vehicle Number SLN 4981 B & SKA 9001 C

CAUTION: This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Dear Sir/Madam,

We are instructed by Lim Shen Loong to notify you of a road traffic accident on 31/07

/2021

at about 16:15R along Junction of Stevens Road & Draycott Drive involving our client's vehicle registration number SLN 4981 B and vehicle registration number SKA 9001 C driven by your insured at the material time.

A copy of the Singapore Accident Statement/Traffic Police Report filed is enclosed. As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated time, our client shall proceed to repair the vehicle without further reference to you.

Please contact me @ 9450 7920, should you require more information.

Kindly arrange survey at Blk 15 Kaki Bukit Road 4, Bartley Biz Centre, #01-53, Singapore 4178

08.

Warmest Regards,

Elin Cai

Zoom Autowerks Pte Ltd

130 Bedok Reservoir Road

#08-1339 Singapore 470130

📞 9450 7920

✉️ zoomautowerks@gmail.com

- Please note our change in mailing/registered address with effect from 1st July 2018 -