

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SLN 4981B*at Workshop m/s *700M*

of _____

Insured: *SKA 9001C*

Policy No. _____


Claims No. *M12D16292108*

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: *\$ 86k.*

IDAC Accident Report: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: *7* days Res.: Yes or NoLum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

*871B*Veh No: *SLN 4981B* Yr Regn: *05/05/17*Type: *M.Car* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or *CAI*Make: *Toyota Corolla* C.C. *1986*Colour: *Purple* A/C: *Insured / Std / NI / NA*Sp. Reading: *36985* T/Radio: *Insured / Std / NI / NA*

Eng/No: _____

C/No: *254 60007 6678*Gen. Cond: *Good / Fair / Poor / Burnt*Steering: *Inorder / Jammed / Leaked / Burnt* or *collected*Brake: *Inorder / Jammed / Leaked / Burnt* orModi: *Nil / S/Rim / STD A/Rim* orTyre Size: F: *235/55-215*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *Continental*

Front

R/Bal. *7* mm R/Bal. *7* mmL/Bal. *7* mm L/Bal. *7* mmD.O.A. *31/7/21* D.O.I. *31/8/21*

Survey held at _____

Des. of Damages: *Frt / Rear / O/S / N/S / UIC / Rooftop* or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

*LTA \$ 59416 Rep 12k**nett \$ 26584**heckley 6714.50. fig lap 516 Bonnet 198390 Under 144630**27/9/21 confirmed 1/5 \$ 14,000 with 7 repair days*

(RED \$9160.67; 40%)

Date/Time, File Pass to?

☐

: Preli. Report

1) 28/9 TYPIST

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: *7*Resurvey No. of Trip: *2*

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) \$ - RS \$

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format: TP

Lump Sum / *14000* (\$ 14000)

TOTAL

Submit to insurance.



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

Tel: 9450 7920

zoomautowerks@gmail.com

Car Number: SLN4981B

Model : Toyota Harrier

Damaged Area: (Front Right Portion)

Repairer Estimation Cost of Repair :

Supplementary may be included during the cost of repair :

not Authorized
here

3/8/21

2/5 @ 14,000 / 7 days

Parts / Material :

1	Front bumper	Dis	811.30	\$ 1,480.10	✓
2	Front bumper lower lip	Dis		\$ 378.10	✓
3	Front bumper fog lamp rh	CNE		\$ 359.10	✓
4	Front bumper fog lamp cover rh	SNO		\$ 110.10	✓
5	Front bumper centre lower grille	TOIN		\$ 365.00	✓
6	Front bumper bumper bottom garnish	Dis		\$ 187.10	✓
7	Front bumper side retainer rh	CNE		\$ 98.10	✓
8	Front bumper side beam rh	Bent		\$ 74.70	✓
9	Front bumper side beam sponge rh	TOIN		\$ 108.60	✓
10	Front bumper clips	NEU		\$ 60.00	✓
11	Radiator grille assy	CNE	1351.40	\$ 1,454.60	✓
12	Headlamp panel rh	Bent		\$ 398.20	✓
13	Headlamp assy rh (HID)	CNE		\$ 3,303.10	✓
14	Headlamp lower bracket rh	CNE		\$ 58.70	✓
15	Front bumper reinforcement	Bent		\$ 486.70	✓
16	Front fender rh	Dis		\$ 1,012.70	✓
17	Front fender cowl rh	TOIN		\$ 421.10	✓
18	Front fender cowl clips	NEU		\$ 50.00	✓
19	Front fender top outer garnish RH	mis		\$ 195.80	✓
20	Front fender wheel house inner panel rh	R		Repair	X
21	Rocker garnish rh	Dis		\$ 386.90	✓
22	Rocker garnish clips	NEU		\$ 50.00	✓
23	Front bonnet	Bent/2uc		\$ 1,486.70	✓
24	Front support panel top garnish	Dis/YMI		\$ 286.70	✓
25	Front support panel top garnish clips	NEU		\$ 45.00	✓
26	Front impact sensor	CNE		\$ 386.70	✓
27	AC condenser pipe inlet	Bent		\$ 325.60	✓
28	AC condenser pipe outlet	11		\$ 395.60	X
29	AC condenser	Dis/CNE		\$ 1,254.80	✓
30	Front door top hinge rh	11		\$ 78.90	X
31	Front door bottom hinge rh	11		\$ 76.50	X
32	Front door garnish RH	11		\$ 78.20	X
33	Front door outer chrome protector rh	11		\$ 198.70	X
34	Front door outer chrome garnish clips	11		\$ 30.00	X
35	Front wheel sport rim rh	Dis/warped		\$ 1,640.30	✓
36	Washer tank & motor.	Dis		\$ 325.60	✓
37	Front knuckle arm rh	Bent		\$ 587.70	✓
38	Front knuckle hub w/bearing rh	Dis/2uc	385	\$ 553.30	✓
39	Front shock absorber rh	Bent		\$ 475.70	✓
40	Front lower arm rh	Bent		\$ 679.20	✓
41	Front steering rack & pinion	SVC		\$ 1,946.70	X
42	Front Driveshaft RH	Bent/2uc		\$ 1,257.60	✓

800 s/w

43 Front stabilizer linkage rh
front support panel

but
but/rim \$407.30 ✓

\$ 146.70
Parts : \$ 23,296.90
Less Parts 25% : \$ 5,824.22
Total Parts : \$ 17,472.67

Special Net Items :

Front tyre rh 647/201
Radiator coolant 11
Front number plate w/garnish 11

LP 220 x 702

\$ 580.00 184 s/w
\$ 110.00 X
\$ 68.00 X
Total S/N Parts : \$ 758.00

Labour :

To Remove, Replace, Re-align & Install affected Front & Side Damaged Areas
To Putty, Prep & Re-spray on affected Front & Side Damaged Areas
To Remove & Transfer Front Doors Components, to Facilitate Repairs
To Discharge & Top Up AC Gas
To Conduct Computerize Full Wheel Alignment
To Remove & Refit Front Tyres, To Replace Rims & Balancing
To Remove, Renew & Refit Front Undercarriage Components
To Reset & Re-programme Management Diagnostic
To Apply Undercoating on the Affected Damaged Areas

\$ 1,600.00 1100
\$ 1,600.00 1100
11 \$ 150.00 X
\$ 150.00 100
\$ 180.00 60
11 \$ 150.00 X
\$ 450.00 350
\$ 450.00 50
\$ 200.00 80
Total Labour : \$ 4,930.00

TOTAL PARTS : \$17,472.67
TOTAL SPECIAL NET ITEM : \$ 758.00
TOTAL LABOUR : \$ 4,930.00
TOTAL REPAIR COST : \$23,160.67

DATE OF SURVEY / INSPECTED:

RECOMMENDED PART BY PART / LUMP SUM :

RECOMMENDED NUMBER OF DAYS :

SURVEY BY / SURVEYOR FIRM :

RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :

FINALISED AMOUNT :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-18317
253/
P-1373775
S.N-954
L-2880
1753175
2020
14028

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	871B
Vehicle Details	
Vehicle No.:	SLN4981B
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Aug 2021
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER PREMIUM STYLE MAUVE 2.0 A
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	3ZRB770872
Chassis No.:	ZSU600076678
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$32,493.00
Original Registration Date:	05 May 2017
First Registration Date:	05 May 2017
Transfer Count:	1
Actual ARF Paid:	\$37,491.00 18745
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 May 2027
PARF Rebate Amount:	\$28,118.00
Intended COE Rebate Details	
COE Expiry Date:	04 May 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$54,406.00
COE Rebate Amount:	\$31,298.00
Total Rebate Amount:	\$59,416.00

The information contained herein is correct as at 03 Aug 2021

OK

CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find out more



Post an Advertisement

Sell it yourself! Advertise it at just
\$68 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Toyota Vios With 5 Years COE RENEWAL.

2.5% P.A. By Gv Cars Financing.
\$0 Down Available. 2 Years
Warranty Coverage.
GV Credit Pte Ltd StarAd

One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars

30 years of car sale

Browse by Category

< Back (1 2 3) Next >

Sort by Date Posted 20 results/page

48 vehicles

harrier

Advanced Search Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	harrier	Any	Any	2017	Any	Any	Any	Available
	Toyota Harrier 2.0A Turbo G Panoramic	\$105,000	\$13,290 /yr	27-Nov-2017	1,998 cc	25,000 km	SUV	Available
Low Mileage. Full Agent Maintain. Highest Specification G Grade Model. Flexible Loan And Instalment Available! Please Contact Direct Sa...								
Posted: 02-Aug-2021 Tags: 2017 Toyota Harrier, Toyota Harrier, Toyota, Harrier								
	Toyota Harrier 2.0A Elegance Panoramic	\$86,888	\$13,170 /yr	09-Feb-2017	1,986 cc	56,000 km	SUV	Available
Latest Arrival! Most Valued Buy! Beautiful White Unit With Original Condition! Peace Of Mind! Serviced Regularly. 100% Accident Free! L...								
Posted: 02-Aug-2021 Tags: 2017 Toyota Harrier, Toyota Harrier, Toyota, Harrier								
	Toyota Harrier 2.0A Elegance Panoramic	\$87,800	\$12,990 /yr	13-Apr-2017	1,986 cc	66,000 km	SUV	Available
Latest Arrival, Beautiful Unit With Immaculate Condition! Buy With A Peace Of Mind With One Year Warranty By Our In-House Workshop...								
Lay Auto Pte Ltd								
Posted: 02-Aug-2021 Tags: 2017 Toyota Harrier, Toyota Harrier, Toyota, Harrier								
	Toyota Harrier 2.0A Turbo G Panoramic	\$108,800	\$14,150 /yr	29-Nov-2017	1,998 cc	50,000 km	SUV	Available
Mileage 50K Km Only Under Agent 5 Years Warranty, 1 Owner, Fully Toyota Agent Serviced With Records, Accident-Free, Nice Paint Ext...								
Posted: 02-Aug-2021 Tags: 2017 Toyota Harrier, Toyota Harrier, Toyota, Harrier								
	Toyota Estima Force Front 6/Rear 4 Pot BBK Big Brake Kit							
"FORCE" Front 6/Rear 4 Pot BBK setup (Big Brake Kit) for Toyota Estima								
More info about this product								
	Toyota Harrier 2.0A Elegance Panoramic	\$90,800	\$12,750 /yr	06-Jul-2017	1,986 cc	70,000 km	SUV	Available
Brand New Condition, Spacious SUV With Panoramic Glass Roof, One Owner Only, Accident Free, Flexible Bank/ In-House Loan Package...								
Posted: 02-Aug-2021 Tags: 2017 Toyota Harrier, Toyota Harrier, Toyota, Harrier								
	Toyota Harrier 2.0A Elegance Panoramic	\$87,888	\$12,850 /yr	20-Mar-2017	1,986 cc	124,048 km	SUV	Available
\$0 Admin Fee For Bank Loan! Fierce And Powerful Toyota Harrier 2.0A Elegance! This Car Promotes A Sporty And Sexy Look Both On Th...								
Carro								
Posted: 02-Aug-2021 Tags: 2017 Toyota Harrier, Toyota Harrier, Toyota, Harrier								

Compare

Compare