

RE: CTI-Re-inspection SJA 3311J (OUR REF: CS3/CTI21003352/R1td3-1)

Simon Ho (LKKAuto) <SimonHo@lkkauto.com>

Wed 4/8/2021 9:10 AM

To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>

Hi Denise,

Audit check done for SJA3311J without problem.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Denise Tay (LKKAuto)

Sent: Wednesday, 4 August, 2021 9:04 AM

To: Simon Ho (LKKAuto)

Subject: Fw: CTI-Re-inspection SJA 3311J (OUR REF: CS3/CTI21003352/R1td3-1)

Hi simon,

amend revised estimate for your audit check

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Simon Ho (LKKAuto) <SimonHo@lkkauto.com>

Sent: Tuesday, 3 August 2021 3:55 pm

To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>

Subject: RE: CTI-Re-inspection SJA 3311J (OUR REF: CS3/CTI21003352/R1td3-1)

Dear Shiau Chan,

AUDIT CHECK DONE FOR SJA3311J, FOUND UNDERCARRIAGE PARTS NOT NECESSARY TO REPLACE.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Shiau Chan (LKKAuto)

Sent: Tuesday, 3 August, 2021 2:10 PM

To: Simon Ho (LKKAuto)

Subject: CTI-Re-inspection SJA 3311J (OUR REF: CS3/CTI21003352/R1td3-1)

Dear Simon,

For your audit.

Thank you.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)