



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21008134/Rqf3n2	
			Date: 29/03/2022	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 5611Z	Veh. Inspected	SME 2665M
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/07/21/2072	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	02/08/2021
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI ELANTRA 1.6 GLS AT	c.c	1591
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	KMHD841CMJU764558	Colour	GREY
	Odometer	297749 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	TOURADOR	5 mm
	L/H Front Tyre	195/65 R15	TOURADOR	5 mm
	R/H Rear Tyre	195/65 R15	TOURADOR	5 mm
	L/H Rear Tyre	195/65 R15	TOURADOR	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	31/07/2021	Inspection Date	03/08/2021
	Survey held at	48 TOH GUAN ROAD EAST #01-141		
	Repairer	MTM AUTOMOTIQ PTE LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	