ASS. REC. BY: TOUM CS/MSQ210	08137/Buf3 . Hui Zhen
	GNMENT
From: Date: 4/8/2021 Estimated Cost:	Veh No: CBC 201A Yr Regn: 24/2/2021 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD I/F I WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or 2982
To Inspect Vehicle No: GBC 20/A	Make: Doyota Hiace c.c 3754
at Workshop m/s Bifrost Auto	Colour Silver A/C: Insured / Std / NI / NA
of 8 Kaki Bukit Ave 4 Premier # 01-49	Sp.Reading 18272 T/Radio: Insured / Std / NI / NA
Insured: SMM 4025E	Eng/No: 1KD 8066081
Policy No. 1001428568	C/No: JTFHT02P200251064
Claims No. 260706	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: laorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: NII S/Rim / STD A/Rim or
	Tyre Size: F: 195/15 195R15C
(Policy Condition)	R: 195/15 195R15C
Remark: The veh had commenced its N/S O/S	BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or
Bal. or Market Value: \$2,5000	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 6 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 6 mm L/Bal. 6 mm
Est. Repairs: 5 days Res.: Yes or No	D.O.A. 24/7/2021 D.O.I. 4/8/2021
Lum Sum: 20 % 3 Val.: Yes or No	Survey held at By 10-84 Au to
CA / REV / REP. / 24 HRS (ND	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OU	The U/C / Chassis frame / Body Structure affected due to collision.
Date:Person Contacted:	The U/C / Chassis frame / Body Structure allosted door to content
Date / Time Action / Instruction Rayae 3,900/2 - 4000/2	
17/8/2021 Revise to MSIG via Merimen.	3600, 5 repair days
Recommended CAR is LS:	\$ 5,250 /2 TOTEN IM
(RED \$4401.13; 55%)	14/8/2021
111/ 92 meda	
NV 82,000/2	Total Illu
NV 48.871/2	4/8/2021
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 5
	Resurvey No. of Trip: 2 Survey Fee:
1) 30/9 TYPIST : Final Report Date/Time, File Return to?	Transportation:
Add F	ee: : Site Insp (\$)S+RSSI
Pide I	ee: Site insp (w
2)	ee: Site insp (\$) Photos
Represent: TP	Go

\$3600

Lump Show 1 1.0.1: (%

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAORE 415875

Fax: +65 64524584

Company Reg No: 201929175W

	<u>Estimate</u>	Vehicle No: Model and make:	GBL201A Toyota Hiace
0			7021
Qty	Spare parts		List price
1	Tailgate		2000
1	Tailgate centre emblem		\$ 1755.90 2,032.50 D
1	Tailgate lock		\$ \sqrt{71.60 N}
1	Tailgate lock catch		√263.00 J _N
1	Rear bumper		\$ 70.20 NJ
4	Rear bumper lower brackets		\$ 374.45 454.30 DI
1	Rear bumper RH side retainer		\$ 180.40 N
1	Rear bumper LH side retainer		\$ 33.40 66.10
1	RH taillamp assy		\$ 33.40 66.10 N
1	RH taillamp lower cover		\$ 33.40 66.10 No
1	RH taillamp lower cover retainer		157.00
1	End panel (outer)		20.00
1	End panel top moulding		
1	End pamel RH side panel		
1	Exhaust pipe		
1	Exhaust pipe gasket		$\frac{$467.60}{$35.10}$ N
		-25%	\$\\\ \begin{array}{c} 1045.75 & 1,470.38 \\ 4,411.13 \\ \overline{3137.25} \end{array}
Oty	Spare parts		Special Nett price
1	Tailgate windscreen glass sealant		\$ 30.00 80.00 NE
1	Tailgate windscreen glass inner seal		\$ 30.00 50.00 NE
1	Tailgate "70Km/h" sticker		
lset	Tailgate inner trim board clips		\$ 20.00 30.00 NE \$ 60.00 NE
lset	Rear bumper clips		\$ 30.00 .70.00 N
lset	Rear bumper reverse sensors		
	The samper reverse sensors		200.00 320.00 5
			310.00
	and pointing		
Doul	and painting		
	charges to remove, check, replace and reinstall damages el beating, cut / weld and re-align all affected panels	bodyparts.	\$ 600.00 1,000.00
ray p	painting on affected panels		\$ 600.00 1.000.00

Check wiring and lighting system	\$	80.00 NAX
Apply rust coating chemical on affected panels	\$	X 41 00.08
Remove, replace and reinstall tailgate windscreen glass and sealants to assist repair	\$ 120.00	220.00
Remove and replace tailgate inner parts to new tailgate	\$ 60.00	100:00
Remove and reinstall rear inner trim and boards to assist repair	\$	-280.00 NNX
Remove, replace and adjust rear bumper reverse sensor to assist repair	\$ 60.60	100.00
Remove and replace exhaust silencer and gasket to assist repair	\$ 50.00	120.00
	1490.00	

Survey & Resurvey on the same day 4/8/2021 12 30 hrs Tolin lin

Lump sum repair Repair day 5

Parts 3137.25 SN 310.00 Labour 1490.00 4937.25 @20% 987.45 3949.80

Total: \$

LKK Auto Consultants hence notify the Repairer of the following:

• To resurvey before/after spray painting

• To display damaged part(s) during resurvey

- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

COR LS \$3950 ~

Talin lini 14/8/2021

8,001.13



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Authorised Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate actions the part of the insurance companies. 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudint policy liability.

4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for Investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesald.

ACCIDENT STATEMENT

Date of Submission Date of Accident **Exact Location of Accident** Additional Location Information Country/State of Loss

28/07/2021 10:04 (SGT) 24/07/2021 12:00 (SGT) Singapore Sim Drive and Lor 17 Geylang junction Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

GBL201A

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner Company Reg No **Email Address** Mobile Phone No Alternative Phone No

Yes PRIBOY SHIPPING SUPPLIES PTE LTD 201706041H saif.ali.khan@priboyshipping.com (Phone) +65-92370795 +65-92370795

VEHICLE PARTICULARS

Manufacturer Model Variant Exact purpose for which vehicle was being used at time of

Are you claiming under your own insurance policy for repair to your vehicle?

Vehicle Category Transmission CC

Employment

Toyota

Hiace

2000

No - Claiming third party Commercial vehicle Auto

INSURANCE COMPANY

Name of Insurance Company Type of Coverage Fleet Policy **Policy Number** Cover Note Number

NTUC Income Insurance Co-operative Ltd Comprehensive No 5120994831

DRIVER

Name of Driver NRIC No

MUHAMMAD JUFRY BIN SEHAT S9233548H



Date Of Birth 11/09/1992 Occupation Outdoor Date Of Driving Pass 22/02/2013 Driving experience 8 YEARS AND 5 MONTHS Gender Male Mobile Number (Phone) +65-87491814 Alt. Phone Number **Email Address** babychipmunk43@gmail.com Address APT BLK 632A SENJA ROAD Address complement #04-167 Postcode S671632 Is the driver the policyholder? No If No, Relationship of the Driver with the Insured **Employee** Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Insurance Company of Other Vehicle Owned by Driver

Type of Accident Collision - Head to Rear Weather Conditions Clear Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?

No
Number of vehicles involved in the accident

Was anybody injured in the Accident?

Was any injured conveyed to hospital by ambulance?

Was any other vehicle or property damaged?

Number of Passengers (Including Driver)

Has the driver been approached by unknown person(s)

soliciting/offering accident claims assistance?

No

DETAILS OF POLICE ACTION

Was the accident reported to the police?

Was notice of intended Prosecution given?

No
If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

Refer to sketch plan

ATTACHMENT(S)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

No
Was there any audio recorded?

No

DETAILS OF OTHER VEHICLE PROPERTY 1

 Vehicle Registration Number
 SMM4025E

 Vehicle Manufacturer

 Vehicle Model

 Vehicle Variant

 Vehicle Colour


 Vehicle Category
 Private car

 Name of Driver
 ONG CHAU YUH

 NRIC No
 \$7813435F

 Contact Number
 (Phone) +65-97587582

 Address



Let 17 Geylang		A: GBL 201A
		B: smmtoss
<u> </u>	<u> </u>	
	国	
SIM Or	V	
DESCRIBE CIRCUMSTANCES OF THE ACCIDENT		
I was waiting for the tr	affic to el	ear along Lor 17
Geylang, while my vehic	k is still s	Parlonary I felt
as impact from my 1852	L net W	own and check
and notice vehicle 18 col	nded onto 3	my venicle
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
The second secon		
2007		
		Name of the second
DECLARATION I/We declare the foregoing particulars are true in every resp.		A Company of the Comp
Sould be true in every rest	LE No. No.	
Policyholder's Signature Oriver Agristure Date & Time (If driver is not the p	olicyholder	Reporting Centre Personnel's Signature
7.5 v lime: 7.3	0910 hx	Name Europea Colic NAME/TRANS SAT 1883

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Company 041H GBL201A No 04 Aug 2021		
041H GBL 201A No		
GBL201A No		
No		
04 Aug 2021		
TOYOTA		
HIACE VAN TURBO 4DR AT		
Silver		
2020		
1KDB066081		
JTFHT02P200251064		
\$29,353.00		
24 Feb 2021		
24 Feb 2021		
0		
\$1,468.00		
No		
\$0.00		
23 Feb 2031		
C - Goods Vehicle & Bus		
10		
\$34,667.00		
\$33,129.00		
\$33,129.00		

The information contained herein is correct as at 04 Aug 2021

OK

MV 82,006/2 PV 33,129/2 NV 48,871/2

TGCim Min 4/8/2021

SGCARMART.COM

Login Sign up

New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

Post an Advertisement Sell it yourself! Advertise it at just \$68 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Toyota Hiace

Bank Loan @ 1.88% In-House Loan Available!

Beautiful & Elegant White Paintwork! Luxurlous Leather Seats! SportyRS Body Ki Art Automobiles Pte Ltd StarAd

HIN LUNG AUTO One Stop Car Hub Finance, Insurance, Workshop New and Used Cars

Browse by Category

« Back (1 2 3 4 5 6 7 8 9 10) Next »

Sort by Reg. Date

✓ 20 results/page ✓

197 vehicles



Advanced Search C

Search

Depreciation

Reg Date

Eng Cap

Veh Type

Status

Search Selection

Toyota Hiace

Price Απν

Απν

Anv

All

Toyota Hiace 3.0A Fuel Type: Diesel

\$84,688

\$8,880 /yr

15-Feb-2021

2,982 cc

12 km

Van Available

Toyota Hiace 3.0A! Ready Stock, Ready On Road! 100% Loan For Both Bank Or Inhouse Is Available. Maximum Tenure Up To 7 Years. We Specialist In Commercial Vehicles Sale And Commercial Vehicle Financial Assistance. Call Our Friendly Sale Person For More... Posted: 01-Jul-2021 Tags: 2021 Toyota Hiace, Toyota Hiace, Toyota, Hiace

Toyota Hiace 3.0A

\$84,688

\$8,880 /уг

15-Feb-2021

2,982 cc

9 km

Van

Any

Available

Fuel Type: Diesel

Up To 100% Loan For Both Bank Or In House Is Available, Attractive Interest Rate For Maximum 7 Year Tenure, High Trade In For Ur Used Vehicle, Wide Range Of Ready Brand New And Used Vehicle For Sale, Call Our Friendly Sale Person For The Best Advise!

Posted: 30-Jun-2021 Tags: 2021 Toyota Hiace, Toyota Hiace, Toyota, Hiace



Toyota Hiace 2.8A DX Fuel Type: Diesel

\$83,688 \$8,800 /yr 05-Feb-2021

2.754 cc

11 km

Available

Last PI Auto Unit! Ready Stock! Toyota Hiace DX 2.8 (Auto) 5DR. Diesel Engine! Silver Colour! Glass Panel. Need LOAN Assistance? 100% Bank Or Inhouse Is Available. Max 7 Year Tenure At Attractive Interest Rate. Call Today To Get A Test Drive And Physical To...

Posted: 22-Jun-2021 Tags: 2021 Toyota Hiace, Toyota Hiace, Toyota, Hiace



Toyota Hiace 2.8A DX

\$90,800

\$9,550 Ar

04-Feb-2021

2,754 cc

Bus

Available

PREMIUM AD

Almost Brand New SDr Bus! For Your Company Usage! Customized Seats Of Your Needs From 6 To 10 Seater! Don't Missed Out This Good Deal! Call Us Now! Door Step Viewing Is Available!

Fuel Type: Diesel

Posted: 13-Jul-2021 Tags: 2021 Toyota Hiace, Toyota Hiace, Toyota, Hiace



Roof Spoiler

Roof Spoiler (Toyota Mark X). Good fitment. Using high quality Material.

More info about this product



Toyota Hiace 2.8A Super GL

04-Feb-2021

2,754 cc

SOLD

Dark Prime Fuel Type: Diesel

Latest Arrival 2020 Super GL Dark Prime II Edition, Latest Facelift With Enlarged Side Mirror, Digital Dashboard. Factory Full Wrapped Interior With Luxurious Look Exterior. Easy Loan Approval, Limited Stock Call Now.

PREMIUM AD

Think One Automobile & Trading

Posted: 21-Jun-2021 Tags: 2021 Toyota Hlace, Toyota Hlace, Toyota, Hlace



Toyota Hiace 2.8A GL

1st Owner, \$10k CVES Rebate, Grab Your Diesel Van Now Before CDE Goes Up Again, Ready CDE/ETS, 5Yrs Warranty + 8x Free

03-Feb-2021

2,755 cc

Van

SOLD PREMIUM AD

Servicings, Real Price Honest Deal, Loan Finance Up To 100%, Lowest Interests, Call To Fix An Appointment With Us Today,

Fuel Type: Diesel

Posted: 17-May-2021 Tags: 2021 Toyota Hiace, Toyota Hiace, Toyota, Hiace

Toyota Hiace 3.0M

\$86,300

\$9,100 /yr

28-Jan-2021

2,982 cc

100 km

Van

Available

ile:///C:/Users/Fujitsu/Documents/LKK Doc/Used Toyota Cars Singapore Car Prices & Listing - sgCarMart.htm