

Kp AUTOWORX HOUSE

c/o 176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

*Not with work
L1 Sup 810, 200/-
Assembly After Paint
Today*

CJ PENINSULA RESOURCES PTE LTD
c/o 46 Lenton Plain
Singapore 786548

Date: 24-10-17

QUANTITY	PARTICULARS	AMOUNT (\$)
RE: BMW 523i / SLK130H		
1 pc	rear boot lid 1380	R 1,700.00
1 pc	rear boot emblem logo	mc 72.30
1 pc	rear boot open latch	sn 196.60
1 pc	rear boot number plate lamp	sn 50.00
1 pc	rear boot outer garnish	sn 399.60
1 pc	rear boot lock	n 167.40
1 pc	rear boot lock catch	n 83.70
1 pc	rear bumper (M-tech version) 1950	B 2,780.00
25 pcs	rear bumper clips	@ 4.80
2 pcs	rear bumper bracket	@ 60.00
2 pcs	rear bumper side bracket	@ 100.00
1 pc	rear bumper reinforcement 650	@ 347.37
2 pcs	rear bumper reinforcement brackets C 170	
1 pc	rear bumper inner pad	
1 pc	rear bumper lower kit 605	
1 pc	rear bumper sponge	
1 pc	rear bumper top garnish	
1 pc	rear bumper tow cover	
2 pcs	rear bumper reverse sensor C 264.00	
4 pcs	rear bumper reverse sensor garnish	
1 pc	rear end panel	
1 pc	rear end panel garnish 168-60	
1 pc	rear exhaust silencer 1180	
2 pcs	rear exhaust silencer rubber mount	
1 pc	rear exhaust heat shield	
2 pcs	rear tail lamp assy C 521.30	
2 pcs	front seat head rest C 760.00	
		sub-total 19,988.34
		less 10% 1,998.83
		sub-total 17,989.51

Balance brought forward	17,989.51
To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.	1000 1,600.00
To check wiring system and reset ECU.	200 100.00
To apply putty and spray painting on affected areas.	800 1,200.00
To apply rust proofing on affected areas.	600 150.00
To apply waterproof sealant on affected areas.	300 150.00
To install reverse sensor and reset ECU programme.	1200 300.00
To remove carpet & trimming to enable repair.	800 120.00
To carry out exhaust works.	800 150.00
To reset SRS system.	1200 220.00
Total	21,979.51

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

CJ PENINSULA RESOURCE PTE LTD
c/o 46 Lenton Plain
Singapore 786548

Date: 14-11-17

QUANTITY	PARTICULARS	AMOUNT (\$)
	<u>RE: BMW 520i / SLK130H / SUPPLEMENTARY</u>	
2 pc	front seat head rest charger	Per 316.50 X
1 pc	PDC control unit	Per 465.00 ✓
1 pc	rear end panel centre dust cover	Per 299.60 X
1 pc	rear end panel RH dust cover	Per 278.00 ✓
1 pc	spare tyre/tools foam box 286.10	Per 415.00 ✓
1 pc	spare tyre/tool foam cover	Per 202.00 X
	Sub-total	1,976.10
	Less 10%	197.61
	total	1,778.49