



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21008143/Knf3e2	
			Date: 05/08/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YQ 2879H	Veh. Inspected	GBK 6253R
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2102234/MYE	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	03/08/2021
2. Vehicle Particulars & Condition				
	Make & Model	VOLKSWAGEN TRANSPORTER (A)	c.c	1968
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	WV1ZZZ7HZKH197362	Colour	RED
	Odometer	36107 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/65 R16	GOODYEAR	3 mm
	L/H Front Tyre	215/65 R16	GOODYEAR	3 mm
	R/H Rear Tyre	215/65 R16	GOODYEAR	9 mm
	L/H Rear Tyre	215/65 R16	GOODYEAR	9 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	27/07/2021	Inspection Date	30/08/2021
	Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	