



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21008149/Auf3n2	
			Date: 12/11/2021	
			Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SG 6025C	Veh. Inspected	SLX 7606M	
Policy No.		Coverage (\$)	0.00	
Claim No.	BUS/07/21/5039	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	03/08/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	AUDI A6	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	WAUZZZ4GXHN128184	Colour	GREY	
Odometer	75971 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/55 R17	HANKOOK	6 mm	
L/H Front Tyre	225/55 R17	HANKOOK	6 mm	
R/H Rear Tyre	225/55 R17	HANKOOK	6 mm	
L/H Rear Tyre	225/55 R17	HANKOOK	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	28/07/2021	Inspection Date	04/08/2021	
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>5 Working Days</b>	