



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:STACEY NG			Ref: CC4/ASM21008154/Vrs3q2 Date: 12/11/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SML 9798E	Veh. Inspected	SJJ 5907E	
Policy No.	P2404938	Coverage (\$)	0.00	
Claim No.	S1M03ESK	Excess (\$)	0.00	
Assign From		Assign Date	03/08/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA ACCORD 2.0 A	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	CL73302256	Colour	BLACK	
Odometer	156406 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	255/40Z R18	PIRELLI	5 mm	
L/H Front Tyre	255/40Z R18	PIRELLI	5 mm	
R/H Rear Tyre	225/40Z R18	PIRELLI	5 mm	
L/H Rear Tyre	225/40Z R18	PIRELLI	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/07/2021	Inspection Date	03/08/2021	
Survey held at	8 KAKI BUKIT AVENUE 4 PREMIER @ KB #02-13			
Repairer	AUTO MEGA MALL PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	