

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

NOT Withheld
L1 Rep & 5100k.
Recovery After Paint
4 Days

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 02.08.2021

Accident Date : 30.07.2021

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Citroen C4" Reg. No. SKU5362G Claiming Against Your Insured Reg. No. SLV9057U		
1pc	Rear Bumper	4.50	965.00 ✓
14pcs	Rear Bumper Clips		63.00 ✓
1pc	Rear Bumper Sponge	150.00	120.00 X
2pcs	Rear Bumper Brackets		300.00 X
1pc	Rear Bumper Reinforcement		475.00 ✓
1pc	Rear Bumper Center Core		173.00 ✓
1pc	Rear Bumper Lower Diffuser Cover	65.00	420.00 ✓
2pcs	Rear Bumper Lower Diffuser Cover Retainers	265.00	130.00 X
2pcs	Rear Bumper Reverse Sensors	55.00	530.00 ✓
4pcs	Rear Bumper Reverse Sensor Holders		220.00 ✓
1pc	Rear Bumper Reverse Sensor Wiring Harness		650.00 X
1pc	Rear Bumper Boot Inner Sensor		165.00 X
1pc	Rear Bumper Tow Point Cover		60.00 ✓
1pc	Front Bumper	4.50	970.00 ✓
12pcs	Front Bumper Clips		54.00 ✓
1pc	Front Bumper Top Moulding (1)		250.00 ✓
1pc	Front Bumper Top Moulding (2)		250.00 ✓
1pc	Front Bumper Center Bracket		270.00 X
1pc	Front Bumper Sponge		105.00 X
1pc	Front Bumper Reinforcement		520.00 ✓
1pc	Front Bumper Center Air Grille		220.00 ✓
1pc	Front Bumper Center Air Grille Inner Air Guide		265.00 X
1pc	Front Bumper Lower Air Grille		290.00 X
2pcs	Front Bumper Lower Inner Brackets(Plastic)	110.00	220.00 ✓
1pc	Front Bumper Lower Air Grille Chrome Surround		280.00 X
1pc	Front Bumper Tow Point Cover		65.00 ✓
1pc	Front Bumper Inner Core		185.00 ✓
1pc	Front Signal Lamp Chrome Moulding LH		210.00 ✓
2pcs	Headlamps	1,080.00	2,160.00 X
2pcs	Headlamp Chromes	220.00	440.00 X
1pc	Front Support Panel Center		650.00 X
1pc	Radiator		1,170.00 X
1pc	Condenser		985.00 X
1pc	Turbo Intercooler		1,350.00 X
	Less 10%		15,180.00
			1,518.00
			13,662.00
		C/F	13,662.00

N.C

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 02.08.2021

Accident Date : 30.07.2021

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Citroen C4" Reg. No. SKU5362G Claiming Against Your Insured Reg. No. SLV9057U		
		B/F	13,662.00
	Tailgate Lower Garnish Badge C&C		60.00 SN
	Front Number Plate		45.00 SN
	To Conduct Rear Electrical Check, Replace Reverse Sensors, Wiring, Reprogramming etc		150.00
	To Conduct Front Electrical Check, Locking System, Adjust, Focus Headlamp etc		40.00
	To Remove / Refit Air Con Condenser & Refill Air Con Gas		120.00
	To Remove / Refit, Radiator System, Bleed, Refill Coolant & Intercooler		150.00
	Labour Charge - Panel Beating, Repairing of Tailgate, End Panel, Bonnet, Support and Parts Replacement		1,200.00
	To Respray Affected Areas (Big Veh)		1,200.00
		Total :	16,627.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: