

**Appraisals Associates Pte Ltd** (Co.Reg.No:201707686W)

2 Sims Close, #06-14 Gemini@Sims  
Singapore 387298  
Tel: 67472822 Fax: 67470070 Email: info@aaplpro.com

**VEHICLE DAMAGE INSPECTION REPORT**

**Our File No:** AV-2724  
**Date:** 19/03/2020

**REFERENCE**

Handling Insurer:	Aviva Ltd	Policy No:	10954388
<b>Claimant Vehicle No :</b>	SGP3525R	<b>Insured Vehicle No :</b>	SMR570Y
Date of Loss:	22/02/2020	Nature of Claim:	TP
		Claim No:	G0067439

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SGP3525R</b>	Engine No:	2AZC060615
Make & Model:	TOYOTA ESTIMA, 2.4 (A)	Chassis No:	ACR507033925
Reg. Date:	13/12/2006 (Man. Year: 2006)	Odometer:	199673 km
Colour:	Red		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

**CONDITION OF TYRES**

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

**INSPECTION**

Date of Assignment:	26/02/2020	
Date Inspected:	04/03/2020	Inspected At: LUSH AUTOMOTIVE PTE LTD (HQ) No. 8 Kaki Bukit Avenue 4., #03-47 Premier@Kaki Bukit, Singapore 415875
Estimated Period of Repair:	7.0 days	

**Adjuster:** Faizal S/O Ghulam Mohamed  
Motor Surveyor

**Manager:** Robin Poon  
Director

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**BRIEF CIRCUMSTANCES OF ACCIDENT**

The Insured's vehicle (insured, SNG YUCHAO) and the Third Party's vehicle (driver, DESMOND HOE BENG HWEE) collided along Punggol Par Gold driving range car park on 22/02/2020 @ 19:05.

**CONSISTENCY OF DAMAGES**

Our visual inspection of the vehicle revealed that the damage noted is consistent to the accident as reported.

**SPECIAL REMARKS**

We have not authorized repair.

The repairer did not provide Repair Estimate during our pre-repair inspection. From our preliminary limited physical assessment, the following visible damage was seen; right portion.

For reserving purposes, we would recommend a claim reserve of S\$5,000.00 to S\$6,000.00 and estimated 07 days to repair.

The estimated market value of this vehicle is about S\$62,888.00. PARF/COE Rebate is S\$37,490.00. The Economical Repair Limit is about S\$25,398.00.

This survey was conducted on a "Without Prejudice" basis and the recommended figures are for insurance company reserve purpose only.

We confirmed that the report is prepared on the basis of visual inspection of the damage vehicle before the repairs are being carried out. Hidden damages may not be visible, supplementary items and additional labour may be included during the course of repair.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Pre-Repair Inspection Report and photographs.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Mar 2020)
Parts:	M1-MPV	TOYOTA ESTIMA 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Appraisals Associates Pte Ltd/SGP3525R/19/03/2020 15:03	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Appraisals Associates Pte Ltd/SGP3525R/19/03/2020 15:03. Not valid without Reference section.
---

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Appraisals Associates Pte Ltd/SGP3525R/19/03/2020 15:03. Not valid without Reference section.

< END OF ESTIMATES >