

Estimation

Date
Vehicle
Make/Model
Chassis No.

SMH 3726 Z
MITSUBISHI ATTRAGE
MMBSTA13AKH000618

No.	Description	Unit	Unit Price	Amount
	Parts Replacment			
1	BOOTLID 828	1	\$ 952.00	\$ 952.00
2	BOOTLID LOGO - MITSUBISHI	1	\$ 44.00	\$ 44.00
3	BOOTLID EMBLEM - ATTRAGE	1	\$ 39.00	\$ 39.00
4	BOOTLID EMBLEM - MIVEC	1	\$ 47.00	\$ 47.00
5	BOOTLID EMBLEM - C&C	1	\$ 33.00	\$ 33.00
6	BOOTLID CHROME GARNISH 266	1	\$ 332.00	\$ 332.00
7	BOOTLID NUMBER PLATE LAMP L+R	2	\$ 48.00	\$ 96.00
8	BOOTLID LOCK CYLINDER	1	\$ 76.00	\$ 76.00
9	BOOTLID LOCK 139	1	\$ 298.00	\$ 298.00
10	BOOTLID LOCK CATCH	1	\$ 32.00	\$ 32.00
11	BOOTLID INNER TRIM	1		\$ -
12	BOOTLID HINGE SET	2	\$ 56.00	\$ 112.00
13	BOOTLID WEATHERSTRIP	1	\$ 183.00	\$ 183.00
14	TAIL LAMP L+R 332	2	\$ 376.00	\$ 752.00
15	TAIL LAMP PANEL L+R	2	\$ 75.00	\$ 150.00
16	REAR BUMPER 660	1	\$ 822.00	\$ 822.00
17	REAR BUMPER REFLECTOR L+R	2	\$ 25.00	\$ 50.00
18	REAR BUMPER RETAINER L+R	2	\$ 29.00	\$ 58.00
19	REAR BUMPER REINFORCEMENT BAR	1		\$ -
20	REAR BUMPER BRACKET L+R	2	\$ 28.00	\$ 56.00
21	REAR WINDSCREEN MOULDING	2	\$ 68.00	\$ 136.00
22	REAR FENDER L+R	2	\$ 855.00	\$ 1,710.00
23	REAR FENDER INNER TRIM L+R	2	\$ 163.00	\$ 326.00
24	REAR FENDER COWLING L+R 38	2	\$ 176.00	\$ 352.00
25	END PANEL 412	1	\$ 452.00	\$ 452.00
26	END PANEL TOP GARNISH 150	1	\$ 71.00	\$ 71.00
27	SPAREWHEEL PANEL	1	\$ 921.00	\$ 921.00
28	SPAREWHEEL PANEL TOP BOARD	1	\$ 198.00	\$ 198.00
29	EXHAUST PIPE	1	\$ 581.00	\$ 581.00
30	EXHAUST MOUNTING SET	2	\$ 63.00	\$ 126.00
31	EXHAUST HEAT SHIELD	1	\$ 74.00	\$ 74.00
			Total	\$ 9,079.00
			Less 10%	\$ 907.90
			Total	\$ 8,171.10

S/Nett Items			
--------------	--	--	--

1	BOOTLID INNER TRIM CLIPS		1	100	\$ X n	100.00
2	BOOTLID CHROME GARNISH CLIPS	nec	1	50	\$ 20	50.00
3	REAR NUMBER PLATE		1	100	\$ X n	100.00
4	TAIL LAMP CLIPS	nec	1	50	\$ 20	50.00
5	TAIL LAMP PANEL		2	80	\$ X n	160.00
6	REAR BUMPER CLIPS		1	100	\$ 30	100.00
7	REAR BUMPER REVERSE SENSOR SET		1	300	\$ 200	300.00
8	REAR WINDSCREEN SEALANT		1	150	\$ X	150.00
9	REAR FENDER SEALANT		2	250	\$ X } n	500.00
10	REAR FENDER INNER TRIM CLIPS		2	100	\$ X }	200.00
11	REAR FENDER COWLING CLIPS	nec	2	100	\$ 30	200.00
12	END PANEL SEALANT	nec	1	250	\$ 40	250.00
13	END PANEL TOP GARNISH CLIPS	nec	1	100	\$ 20	100.00
14	SPAREWHEEL PANEL SEALANT		1	300	\$ X n	300.00
				Total	\$	2,560.00

360

	LABOUR				
1	PANEL BEATING ON AFFECTED AREAS	1	2400	\$ 700	2,400.00
2	SPRAY PAINT ON AFFECTED AREAS	1	1400	\$ 700	1,400.00
3	TO RNR REAR WINDSCREEN	1	300	\$ + n	300.00
4	TO RNR REAR EXHAUST	1	250	\$ X n	250.00
5	TO CHECK WIRING AND TAIL LAMP FUNCTION	1	150	\$ 30	150.00
6	TO RNR REAR INNER TRIM AND UPHOLSTERY	1	400	\$ 60	400.00
7	TO CHECK WATER LEAK	1	150	\$ X n	150.00
8	TO RNR FUEL TANK	1	250	\$ X n	250.00
9	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	1	600	\$ X n	600.00
10	TO RNR REAR BOOT MECHANISM	1	350	\$ 60	350.00
11	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	1	150	\$ 30	150.00
12	TO PERFORM RUST PROOFING	1	400	\$ 40	400.00
13	TO RNR REAR DOOR MECHANISM	1	400	\$ X n	400.00
					1620.
	Total Labour			\$	7,200.00
	Parts Replacement Amount			\$	10,731.10
	Total Amount			\$	17,931.10

Tanfahri 97495749
 'WP' 5/8/21 e 1630
 c/s Resurvey after repair
 Tanfahri elkhant.com
 6 days

2781.90
 360
 1620
 4761.90
 1583800
 16 days
 #

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: