

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

LKK-

DATE: 3-Aug-21INSURANCE: NTUC CP(P)MODEL: Hyundai IoniqMVA: LIM T SVEHICLE NO.: SHC 801U - CityCab

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
	Rear Smart Key Antenna	1		\$40.50	Xr
	Rear Bumper	1		\$459.40	X cut
	Rear Bumper Reinforcement	1		\$394.80	X
	Rear Bumper Reinforcement Bracket (LH/RH)	2	\$138.10	\$276.20	X
	Rear Bumper Centre Moulding Assy	1		\$451.25	/cut
	Rear Bumper Lower Centre Moulding Assy	1		\$155.00	X cut
	Rear Bumper Cover Clips	10	\$2.20	\$22.00	/NCC
	Rear Bumper Fog Lamp	1		\$201.50	X cut
	Rear Bumper Towing Cover	1		\$98.80	Xr
	SUB TOTAL			\$2,099.45	473.25
	LESS 20%			\$419.89	
	DISCOUNTED TOTAL			\$1,679.56	378.6
	Rear Bumper Reverse Sensor	1		\$180.00	/cut
	Rear No. Plate W/Trim Cover	1		\$55.00	/cut
	SUB S/NETT			\$235.00	235
	LESS 10%			\$23.50	
	SUB S/NETT TOTAL			\$211.50	211.5
	SPARE PARTS TOTAL			\$1,891.06	540.1
	Labour Charge				
	Panel Beating			\$400.00	350
	Spray Painting Charge			\$300.00	250
	Remove/Refix Reverse Sensor			\$120.00	30
	TOTAL LABOUR			\$820.00	630
	ESTIMATE TOTAL			\$2,711.06	1770.10

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thevan Lhk

wp 2days

82235769

thevan@lkhkauto.com