

### Estimation

Date \_\_\_\_\_  
 Vehicle \_\_\_\_\_  
 Make/Model **MITSUBISHI LANCER**  
 Chassis No. **JMYSTCS3A8U010591**

| No.              | Description                                   | Unit | Unit Price | Amount          |
|------------------|-----------------------------------------------|------|------------|-----------------|
| Parts Replacment |                                               |      |            |                 |
| 1                | FRONT WIPER PANEL GARNISH X un                | 1    |            | \$ 416.00 -     |
| 2                | BONNET HINGE X un                             | 2    |            | \$ 144.00 -     |
| 3                | HEADLAMP L+R <i>RM 09 / HKX un 523</i>        | 2    | \$ 641     | \$ 1,382.00 -   |
| 4                | HEADLAMP BRACKET L+R <i>RMX un 134</i>        | 2    | \$ 77.80   | \$ 155.60 -     |
| 5                | FRONT BUMPER RETAINER L+R X un                | 2    |            | \$ 232.00 -     |
| 6                | FRONT BUMPER REINFORCEMENT BAR <i>bt 134</i>  | 1    |            | \$ 252.60 -     |
| 7                | FRONT BUMPER SPONGE X un                      | 1    |            | \$ 319.00 -     |
| 8                | FRONT BUMPER UNDERCOVER X un                  | 1    |            | \$ 471.00 -     |
| 9                | FRONT FENDER L+R X un                         | 2    | 609.00     | \$ 1,218.00 -   |
| 10               | FRONT FENDER COWLING L+R <i>in @ 107 each</i> | 2    | 201.00     | \$ 403.80 214 - |
| 11               | FRONT SUPPORT PANEL <i>bt 558</i>             | 1    |            | \$ 1,289.00 -   |
| 12               | FRONT SUPPORT PANEL TOP GARNISH X un          | 1    |            | \$ 274.00 -     |
| 13               | AIRCON CONDENSOR X un                         | 1    |            | \$ 786.3 -      |
| 14               | AIRCON CONDENSOR AIR GUIDE L+R X un           | 2    |            | \$ 189.00 -     |
| 15               | RADIATOR X un                                 | 1    |            | \$ 979.00 -     |
| 16               | RADIATOR FAN COWLING X                        | 1    |            | \$ 456.00 -     |
| 17               | RADIATOR FAN BLADE X                          | 1    |            | \$ 376.00 -     |
| 18               | RADIATOR FAN MOTOR X                          | 1    |            | \$ 411.00 -     |
| 19               | WIPER WASHER TANK X                           | 1    |            | \$ 316.00 -     |
| 20               | FRONT HORN <i>bt</i>                          | 1    |            | \$ 74.00 -      |
|                  | <b>1503</b>                                   |      | Total      | \$ 10,243.30 -  |
|                  | <b>1352.70</b>                                |      | Less 10%   | \$ 1,024.33 -   |
|                  |                                               |      | Total      | \$ 9,218.97 -   |

*RM 92574.50*  
*- 10% = RM 2317.05*

|    | S/Nett Items                   |   |      |                  |               |
|----|--------------------------------|---|------|------------------|---------------|
| 1  | BONNET CARBON FIBRE            | 1 | 4000 | \$ X <i>cm</i>   | 4,000.00 1200 |
| 2  | BONNET INSULATOR               | 1 | 200  | \$ X un          | 200.00        |
| 3  | FRONT GRILLE                   | 1 | 900  | \$ <i>cm</i> 200 | 900.00        |
| 4  | FRONT BUMPER TOP               | 1 | 2000 | \$ <i>de</i>     | 2,000.00 800  |
| 5  | FRONT BUMPER LOGO - MITSUBISHI | 1 | 200  | \$ X un          | 200.00        |
| 6  | FRONT BUMPER LOWER             | 1 | 2500 | \$ <i>Ry</i>     | 2,500.00      |
| 7  | FRONT BUMPER FOG LAMP L+R      | 2 | 400  | \$ X un          | 800.00        |
| 8  | FRONT BUMPER TAG               | 1 | 250  | \$ X un          | 250.00        |
| 9  | FRONT BUMPER CLIPS             | 1 | 100  | \$ 30            | 100.00        |
| 10 | FRONT NUMBER PLATE             | 1 | 120  | \$ 45 <i>bt</i>  | 120.00        |
| 11 | FRONT FENDER COWLING CLIPS     | 2 | 100  | \$ 30            | 200.00        |

|    |                                       |   |              |         |                  |
|----|---------------------------------------|---|--------------|---------|------------------|
| 12 | FRONT SUPPORT PANEL TOP GARNISH CLIPS | 1 | 100          | \$ X un | 100.00           |
| 13 | RADIATOR COOLANT                      | 1 | 100          | \$ X un | 100.00           |
|    |                                       |   | <b>Total</b> | \$      | <b>11,470.00</b> |

2305

|    | LABOUR                                        |   |      |              |             |
|----|-----------------------------------------------|---|------|--------------|-------------|
| 1  | PANEL BEATING ON AFFECTED AREAS               | 1 | 1400 | \$ 700       | 1,400.00    |
| 2  | SPRAY PAINT ON AFFECTED AREAS                 | 1 | 1500 | \$ 500       | 1,500.00    |
| 3  | TO CHECK WIRING AND HEADLAMP FOCUS            | 1 | 150  | \$ 30        | 150.00      |
| 4  | TO CHECK WIRING AND FOG LAMP FUNCTION         | 1 | 150  | \$ X un      | 150.00      |
| 5  | TO RNR INNER TRIM AND UPHOISTERY              | 1 | 400  | \$ X un      | 400.00      |
| 6  | TO CHECK WATER LEAK                           | 1 | 150  | \$ X un      | 150.00      |
| 7  | TO RNR FRONT AIR CON CONDENSOR AND TOP UP GAS | 1 | 300  | \$ 100 X un. | 300.00      |
| 8  | TO RNR FRONT RADIATOR                         | 1 | 250  | \$ X un      | 250.00      |
| 9  | TO PERFORM DIAGNOSTIC AND CLEAR FAULTS        | 1 | 600  | \$ X un      | 600.00      |
| 10 | TO PERFORM RUST PROOFING                      | 1 | 200  | \$ 30        | 200.00      |
| 11 | TO RNR HORN AND TEST FUNCTION                 | 1 | 150  | \$ X un      | 150.00      |
|    |                                               |   |      |              | <b>1260</b> |

|                                 |    |                  |
|---------------------------------|----|------------------|
| <b>Total Labour</b>             | \$ | <b>5,250.00</b>  |
| <b>Parts Replacement Amount</b> | \$ | <b>11,470.00</b> |
|                                 |    | <b>25,938.97</b> |
| <b>Total Amount</b>             | \$ | <b>16,720.00</b> |

Tanji 97495747  
 WP 5/8/21 2430p  
 1/3 Resurvey after repair  
 Tanji 97495747  
 6 days

1352.70  
 2305  
 1260  
 4917.70  
 4917.70  
 6 days

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is of a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: