

AFORTDELGRO ENGINEERING PTE LTD

PAIR ESTIMATE*

VEHICLE NO SHA7105K

02/08/21

MAKE :

CHIANG/NTUC

MODEL IONIQ G2

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		R \$459.40
1	REAR BUMPER SIDE BRACKET LH		u 1 X \$55.80
1	REAR BUMPER CENTRE MOULDING		R \$451.25
1	REAR BUMPER REFLECTOR LH		u 4 X \$41.45
1	REAR BUMPER TOW COVER		u 1 X \$98.80
10	REAR BUMPER CLIPS		u 1 X \$22.00
1	REAR REINFORCEMENT STAY HH		u 1 X \$138.10
1	REAR BUMPER REINFORCEMENT		u 1 X \$394.80
	SUB TOTAL		\$1,661.60
	20.00%		\$332.32
	DISCOUNTED TOTAL		\$1,329.28
1	REAR REVERSE SENSOR		u 1 X \$180.00
1	REAR NUMBER PLATE W/HOLDER		u 1 X \$55.00
1	REAR BUMPER MAT		u 1 X \$50.00
			\$212.00
	Labour Charge		
	Panel Beating		350 \$450.00
	Spray Painting Charge		250 \$300.00
	Tuff Kote		u 1 X \$60.00
	Remove/refix Reverse sensor		30. \$60.00
	TOTAL LABOUR		\$870.00
	ESTIMATE TOTAL		\$2,411.28
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

Tarfat 9744 5749
-wp
3/8/21 24pm
Resurvey after repair
2 days
tarfat @ 11am 20.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: