



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: CYNTHIA			Ref: CC4/ASM21008245/R1pa3q2 Date: 18/10/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 9369C	Veh. Inspected	SMY 7239Y
	Policy No.	VFX/P2419140	Coverage (\$)	0.00
	Claim No.	S1M03EZU	Excess (\$)	0.00
	Assign From		Assign Date	04/08/2021
2. Vehicle Particulars & Condition				
	Make & Model	B.M.W. 318I SEDAN LED	c.c	1499
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	WBA8E32050K497891	Colour	BLACK
	Odometer	132972 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	265/30Z R19	FALKEN	6 mm
	L/H Front Tyre	265/30Z R19	FALKEN	6 mm
	R/H Rear Tyre	265/30Z R19	FALKEN	6 mm
	L/H Rear Tyre	265/30Z R19	FALKEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	03/08/2021	Inspection Date	05/08/2021
	Survey held at	MTM AUTOMOTIQ PTE LTD 48 TOH GUAN ROAD EAST, #01-138, ENTERPRISE HUB, SINGAPORE 608586		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	