

NEW HOCK TECK MOTOR PTE LTD

Our Ref : SMF4836T
Your Ref : SLM4671B
Date : 4/8/2021

1 Kaki Bukit Ave 6
Blk C @ Autobay, #01-43
Singapore 417883
Tel : (65) 6747 9241
Fax : (65) 6741 7276

Sompo Insurance Singapore Pte. Ltd.

BY EMAIL

motorsurvey@sompo.com.sg

Attention : Motor Claims Department

Dear Sirs,

DATE OF ACCIDENT : **03 AUG 2021 @ 18:00 hours**

**NOTICE OF INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS
PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES**

We act for **MAO ZHENYU** who has appointed the
undermentioned workshop to repair motor vehicle no. **SMF4836T**

Please be informed that the said vehicle can be inspected at :

**NEW HOCK TECK MOTOR PTE LTD
1 KAKI BUKIT AVE 6
#01-43 BLK C @ AUTOBAY
SINGAPORE 417883**

Contact Person : Office @ 6747 9241 (Yun Li / Sukyi)

If you failed to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday. The said workshop will commence repairs thereafter without further reference to you.

Yours Faithfully



New Hock Teck Motor Pte Ltd

For Surveyor.

Please initial here after completion of
Pre-repair inspection. Thank you

Surveyor Name :
& signature

Date&Time :