

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 58943
Date Estimated : 12/07/2021
Prepared By : Brandon Chan Eng Meng

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Lily Marine Services Pte Ltd
19 Keppel Road
#09-01 Jit Poh Building

Singapore 089058

- ACCOUNT - 158
Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFA3704G	WBATR12060LM17608	30/04/2019	X3 sDrive20i	24225

DESCRIPTIONVALUE

To replace front bumper, front left fender wheel arch cover including to knock out front left fender and dented area caused by the accident

850 2,550.00

To respray front bumper and front left fender

2197 2,218.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

168 177.00

To check electrical wiring system at the front section for proper function including adjustment of headlights.

168 177.00

Sundries.

80.00

Total Labour 1: 5,202.00

DESCRIPTIONQTYPRICVALUE

FRT SHOCK ABSORBER X

1 66.25

66.25

FRT BUMPER TOP CARRIER X?

1 858.75

858.75

LH FOG LAMP SUPPORT

1 54.50

54.50

LH GUIDE BUMPER

1 37.00

37.00

FRT BUMPER LH INSERT

1 57.35

57.35

LH SIDE GRILLE OPEN WITH PDC (NEBEL)

1 92.85

92.85

FRT BUMPER PANEL PRIMED (PMA)

1 1,406.25

1,406.25

EXPANDING RIVET BLACK

30 1.40

42.00

FRT LH WHEEL ARCH TRIM

1 190.65

190.65

LH FOG LAMP LED

1 473.70

473.70

Total Parts : 3,279.30

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64756601 (After Sales)
64756624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 58943
Date Estimated : 12/07/2021
Prepared By : Brandon Chan Eng Meng

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFA3704G	WBATR12060LM17608	30/04/2019	X3 sDrive20i	24225

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time _____ Excess S\$ _____

Surveyor's Name _____ Sign _____

Surveyor's Tel _____ Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend _____

Steve (LKK) ML RL
8322 8813 P/P
11/8/21, 3:00pm My Bel Sy
4 dys

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurer



Knownledged by Repairer
Signature:

Labour 1	:	5,202.00
Parts	:	3,279.30
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	593.69
Grand Total	:	9,074.99

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **