

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Pauline Tham

Date: 10 Aug 2021

**Preliminary Advice**

Insured Vehicle No	: YQ976Z	Accident Date	: 11/07/2021
TP Vehicle No	: SLQ8769G	Assignment Date	: 05/08/2021
Make	: HYUNDAI ELANTRA	Est. Duration of Repair	: 14
Date of Inspection	: 6/8/21		
Inspection At	: AUBURN AUTO PTE LTD		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	31,384.00
Revised Amount	:S\$	9,073.60
Check Items (Estimated)	:S\$	0.00
Total	:S\$	9,073.60
 Lump Sum Repair	 :S\$	 7,250.00

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	15,000.00
COE / PARF Rebate	:S\$	9,853.00
Salvage Value	:S\$	
Margin for Repair	:S\$	5,147.00

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( X ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : The above survey was conducted on a 'Without Prejudice' basis.