Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd. 8 Temasek Boulevard #04-01 Suntec Tower Three

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

From: LKK Auto Consultants Pte Ltd

Singapore 038988

Attn: Date: 10 Aug 2021

Preliminary Advice

Insured Vehicle No : XE6620K

TP Vehicle No : SLA5386G Accident Date : 03/08/2021 Make : NISSAN SYLPHY **Assignment Date** : 05/08/2021

Date of Inspection : 06/08/2021 Est. Duration of Repair : 22

: EM-1 AUTO PTE LTD (HQ) Inspection At

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C, #01-68

SINGAPORE 575643

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 11,120.00 (SN + LABOUR ONLY)

Revised Amount :S\$ 8,655.00 Check Items (Estimated) :S\$ 300.00 Total :S\$ 8,955.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$ Pre-Accident Value :S\$ COE / PARF Rebate :S\$ Salvage Value :S\$ Margin for Repair :S\$

Remarks

)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage	e. Kindly
	let us have your authorisation.	

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject (X) to consistency check, part prices and labour cost.