

1	of 2 ?	100%	Find Next
---	--------	------	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ERGO INSURANCE PTE LTD		Ref: CS3/EG121008278/f3	
8 TEMASEK BOULEVARD, #04-01 SUNTEC		Date: 05/08/2021	
TOWER THREE SINGAPORE 038988		Code: EGI	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	XE 332G	Veh. Inspected	CYCLIST
Policy No.		Coverage (\$)	0.00
Claim No.	CDMFG21001415	Excess (\$)	0.00
Assign From	PAULINE SOH	Assign Date	05/08/2021
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	31/07/2021	Inspection Date	05/08/2021
Survey held at	160 Sin Ming Drive #06-20, Sin Ming Autocity		
Repairer	R C AUTO		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			