



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

STAR AUTO PERFORMANCE PTE LTD

176 SIN MING DRIVE
#04-05 SIN MING AUTOCARE
SINGAPORE 575721

Ref: CS/TP21008281/Kuce2

Date: 27/08/2021

Code: TP535

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	WBA7T22040CE38095
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	30/07/2021

2. Vehicle Particulars & Condition

Make & Model	BMW 740LI (A)	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	WBA7T22040CE38095	Colour	METALLIC PEARL WHITE
Odometer	5480 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/40 R20	PIRELLI	9 mm
L/H Front Tyre	245/40 R20	PIRELLI	9 mm
R/H Rear Tyre	275/35 R20	PIRELLI	9 mm
L/H Rear Tyre	275/35 R20	PIRELLI	9 mm

4. Description of Damages

--

5. General Information

Accident Date	Inspection Date	30/07/2021
Survey held at	STAR AUTO PERFORMANCE PTE LTD 176 SIN MING DRIVE, #04-05, SIN MING AUTOCARE, SINGAPORE 575721	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--