

COMFORT TRANSPORTATION PTE LTD
REPAIR ESTIMATE

Vehicle No. : SHC8763T

Date: 04/08/2021

Make : HYUNDAI

Insurance: NTUC

Model : I-40

MVA: MS. Y Y

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$1,106.00 /cut
1	REAR BUMPER CLIPS			\$22.00 /net
1	REAR BUMPER REINFORCEMENT			nn X \$428.40 ?
1	RR BUMPER REINFORCEMENT BRACKET LH RH		\$160.60	nn X \$321.20 ?
1	REAR BUMPER UNDER COVER			\$228.00 /cut
1	REAR PANEL			nnx \$526.70 ?
1	REAR PANEL GARNISH			\$57.70 /r
	SUB TOTAL			\$2,632.30 1356
	LESS 20%			\$526.46
	DISCOUNTED TOTAL			\$2,105.84 1084.8
1	REAR BUMPER RUBBER MAT			\$50.00 Nett/cut
1	REAR BUMPER REVERSE SENSOR	-10.00%	\$135.70	\$122.13 Nett/cut
				\$172.13 Nett
	Labour Charge			
	PANEL BEATING			\$600.00 350 280
	SPRAY PAINTING CHARGE			\$350.00 250
	REMOVE/REFIX REVERSE SENSOR			\$60.00 30
	TOTAL LABOUR			\$1,010.00 732.13
	ESTIMATE TOTAL			\$3,287.97 1816.93
				-20% = 1452.90
				= 1450 //

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thevan Lkh

wp 2days

82235769

thevan@Lkhauto.com

4/8/21 15:30