



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Ref: CS3/LPC21005988/T1qf3e2-1 Date: 21/09/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YM 6876K	Veh. Inspected	SMT 9696Z
Policy No.		Coverage (\$)	0.00
Claim No.	21/21/21/VC00/024578	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	06/08/2021
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ C 180	c.c	1597
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WDD2040452A585821	Colour	GREY
Odometer	139639 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/40 R18	PIRELLI	6 mm
L/H Front Tyre	235/40 R18	PIRELLI	6 mm
R/H Rear Tyre	235/40 R18	PIRELLI	6 mm
L/H Rear Tyre	235/40 R18	PIRELLI	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	18/05/2021	Inspection Date	19/05/2021
Survey held at	GARAGE 13 PTE LTD 8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	