



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:YVONNE			Ref: CC4/ASM21008334/Uga3q2 Date: 06/12/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLR 5290J	Veh. Inspected	SMH 5572L
	Policy No.	GA261046	Coverage (\$)	0.00
	Claim No.	S1M03F88	Excess (\$)	0.00
	Assign From		Assign Date	10/08/2021
2. Vehicle Particulars & Condition				
	Make & Model	B.M.W. X3 (A)	c.c	1997
	Engine No.	HIDDEN	Year of Reg.	2013
	Chassis No.	WBAWX320000B27691	Colour	BLACK
	Odometer	127021 KM	Steering	AFFECTED
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/50 R18	BRIDGESTONE	6 mm
	L/H Front Tyre	245/50 R18	BRIDGESTONE	6 mm
	R/H Rear Tyre	245/50 R18	BRIDGESTONE	6 mm
	L/H Rear Tyre	245/50 R18	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	06/08/2021	Inspection Date	10/08/2021
	Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	