

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	CHINA TAIPING IN	ISURANCE (S) PTE LTD	R	Ref:	CS/CTI21008355/Atc	
	3 ANSON ROAD # SPRINGLEAF TOV	16-00 VERSINGAPORE 079909	D	Date:	10/08/2021	
			C	Code:	СТІ	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	GBH 931Y	Veh. Inspected		SLQ 4543S	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	SNM21D204391/C02/GBH931Y /LEWLC	Excess (\$)		0.00	
	Assign From	JENNY LEW	Assign Date		10/08/2021	
2. Vehicle Particulars & Condition						
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.	Colour				
	Odometer	Steering	teering			
	Brakes	Modification				
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.	General Information					
	Accident Date	19/07/2021	Inspection Date		10/08/2021	
	Survey held at	XIN HUA WORKSHOP PTE LTD				
		23 KAKI BUKIT AVENUE 4 #04-01 (SOUTH WING) SINGAPORE 415933				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					