



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Ref: CS3/GRB21007764/Etf3e2-1	
			Date: 30/08/2021	
			Code: GRB	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLP 4383S	Veh. Inspected	YP 4083D	
Policy No.	D21MFL0000447	Coverage (\$)	0.00	
Claim No.	MFL2021D0002997	Excess (\$)	0.00	
Assign From	CARINE KEK PHER SER	Assign Date	11/08/2021	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI CANTER	c.c	2998	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	FEB21EA20975	Colour	WHITE	
Odometer	416076 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/85 R15	BRIDGESTONE	4 mm	
L/H Front Tyre	195/85 R15	BRIDGESTONE	4 mm	
R/H Rear Tyre	195/85 R15	BRIDGESTONE	4 mm	
L/H Rear Tyre	195/85 R15	BRIDGESTONE	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/07/2021	Inspection Date	21/07/2021	
Survey held at	NEW PIONEER AUTO 1 SOON LEE STREET #01-50 PIONEER CENTRE			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	