

1	of 2 ?	100%	Find Next
---	--------	------	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref: CS3/LPC21005277/Gqf3-1	
300 BEACH ROAD		Date: 12/08/2021	
#17-04/07 THE CONCOURSE SINGAPORE 199555		Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YM 5064T	Veh. Inspected	GBE 2097H
Policy No.	Z/20/VC00/108156	Coverage (\$)	0.00
Claim No.	20/21/21/VC00/024505	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	12/08/2021
2. Vehicle Particulars & Condition			
Make & Model	c.c 0		
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	Colour		
Odometer	-	Steering	
Brakes	Modification		
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	27/04/2021	Inspection Date	12/08/2021 29/04/2021
Survey held at	MHL AUTOMOBILE SERVICES BLK 3006, UBI ROAD 1 #01-360 SINGAPORE 408700		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			