



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0644/2021/KS
DATE : 11-Aug-21
WIP : 39079

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

5 days - ok - Johnny Boo

27-Sep-21

OWNER'S NAME : MR HEUNG TSZ KIN ULYSSES
ADDRESS : BLK 487A CHAO CHU KANG AVENUE 5
#13-83
SINGAPORE 681487
TELEPHONE : HP +65 97437040
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800153960-01
VEHICLE NO : **SMG 5848 E**
MODEL CODE : AUDI A4 SEDAN2.0 TFSI 8W
MODEL YEAR : 12/26/2018
ENGINE NO : CVK 071121
CHASSIS NO : WAUZZZF4XKN000814
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
DATE OF ACCIDENT : 10-Aug-21
PLACE OF LOCATION : 67 TUAS VIEW LOOP, SINGAPORE 637710

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE.SMG 5845 E.

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS , OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	\$ 480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00	
4	TO DISMANTLEE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. TO RENEW LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,200.00	\$ 1,000.00
5	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$ 2,500.00	\$ 1,100.00
6	TO RENEW LHS FRONT WHEEL SUSPENSION ASSY.	S/N \$ 2,400.00	
7	TO RENEW LHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 520.00	\$ 280.00
6	TO CARRY OUT PRE/ POST DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 12,092.00	\$ 3,052.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMG 5845 E.

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		
			S/NETT		REMARKS
1	FRONT BUMPER	1	\$	1,787.00	\$ 1,429.60
2	FRONT BUMPER FIXING PARTS	1	\$	587.00	
3	FRONT BUMPER SECURING STRIP	2	\$	72.00	\$ 56.32
4	FRONT BUMPER GRILLE CENTER	1	\$	196.00	\$ 156.40
5	FRONT BUMPER CLOSING ELEMENT	1	\$	210.00	
6	FRONT BUMPER AIR GUIDE LH	1	\$	63.00	\$ 50.08
7	RADIATOR GRILLE	1	\$	1,332.00	\$ 1,065.60
8	FRONT BUMPER AIR GUIDE GRILLE LH	1	\$	135.00	
9	FOAM FILLER PIECE	1	\$	124.00	
10	FRONT BUMPER REINFORCEMENT BEAM	1	\$	845.00	
11	FRONT BUMPER GUIDE SECTION LH	1	\$	36.00	\$ 28.72
12	FRONT BUMPER TOP COVER	1	\$	127.00	
13	"CAUTION" STICKER	1	\$	14.00	
14	A/C STICKER	1	\$	8.00	
15	LOCK CARRIER BRACKET	1	\$	137.00	
16	LOCK CARRIER SUPPORT LH / RH	2	\$	58.00	
18	FRONT PARKING AID SESNOR	2		TBC	
19	FRONT PARKING AID SENSOR SEAL RING	1	\$	14.00	
20	FRONT BUMPER WIRING SET	1	\$	510.00	
SUB TOTAL SPARE PARTS		:	\$	6,255.00	\$ 2,786.72

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMG 5845 E

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		
			S/NETT	REMARKS	
		<i>c/f</i>		\$	2,786.72
21	HORN LH	1	\$	12.00	
22	HORN BRACKET LH	1	\$	29.00	
23	FRONT FENDER LH	1	\$	767.00	\$ 613.20
24	FRONT FENDER ATTACHMENT LH	1	\$	202.00	
25	FRONT FENDER CLOSING ELEMENT LH	1	\$	72.00	\$ 57.52
26	FRONT FENDER BRACKET LH	1	\$	35.00	
27	FRONT FENDER DEFORMATION ELEMENT	1	\$	49.00	
28	FRONT FENDER BRACKET LH	1	\$	32.00	
29	FRONT FENDER BRACE LH	1	\$	118.00	\$ 94.40
30	FRONT WHEEL HOUSING LINER LH	1	\$	240.00	\$ 191.60
31	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$	233.00	
32	FRONT WHEEL SPOILER LH	1	\$	73.00	
33	FRONT WHEEL SPOILER TRIM LH	1	\$	35.00	
34	FRONT WHEEL STONE CHIP GUARD LH	1	\$	51.00	
35	FRONT FENDER FLEDGE COVER - LONG	1	\$	31.00	\$ 24.64
36	FRONT FENDER FLEDGE COVER - SHORT	1	\$	23.00	\$ 17.92
37	LED HEADLIGHT - LH	1	\$	7,693.00	
38	LIFT CYLINDER - LH	1	\$	210.00	
39	LIFT CYLINDER HOSE - LH	1	\$	93.00	
40	LOCK CARRIER	1	\$	1,016.00	
TOTAL SPARE PARTS		:	\$	17,269.00	\$ 3,786.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMG 5845 E

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
		<i>c/f</i>		\$ 3,786.00
41	LOCK CARRIER LOWER SUPPORT LH	1	\$ 38.00	
42	RADIATOR COOLANT	6	\$ 266.00	
43	RADIATOR AIR GUIDE LH	1	\$ 28.00	
44	RADIATOR AIR GUIDE LH	1	\$ 12.00	
45	RADIATOR AIR GUIDE CENTER	1	\$ 16.00	
46	RADIATOR AIR GUIDE LOWER	1	\$ 22.00	
47	FRONT LOWER ARM LH	1	\$ 539.00	
48	FRONT SUSPENSION GUIDE LH	1	\$ 943.00	
49	FRONT UPPER ARM LH FRONT	1	\$ 512.00	
50	FRONT UPPER ARM LH REAR	1	\$ 512.00	
51	FRONT WHEEL HOUSING BEARING LH	1	\$ 968.00	
52	FRONT LOWER ARM BALL JOINT LH	1	\$ 193.00	
53	FRONT WHEEL HUB LH	1	\$ 479.00	
54	FRONT WHEEL BEARING LH	1	\$ 246.00	
55	FRONT SUSPENSION FORK LH	1	\$ 264.00	
56	FRONT COUPLING ROD LH	1	\$ 167.00	
57	FRONT GAS SHOCK ABSORBER	1	\$ 301.00	
58	FRONT TIE ROD LH	1	\$ 99.00	
59	FRONT TIE ROD END LH	1	\$ 197.00	
60	FRONT NO PLATE	1	\$ 60.00	\$ 60.00
61	FRONT LHS TYRE	1	\$ 420.00	\$ 420.00
62	FRONT LHS RIM (<i>Owner</i>)	1	\$ 1,100.00	\$ 1,100.00
63	SUNDRIES	1	\$ 400.00	\$ 15.84
TOTAL SPARE PARTS		:	\$ 29,386.00	\$ 5,381.84
TOTAL LABOUR CHARGES		:	\$ 12,092.00	\$ 3,052.00
GRAND TOTAL		:	\$ 41,478.00	\$ 8,433.84

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

bl-18/09/21



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT