



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21008443/Uqf3n2	
			Date: 29/09/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLC 5078K	Veh. Inspected	SMN 4797E	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2102359/SYH	Excess (\$)	0.00	
Assign From	MELVIN YE YONG KANG	Assign Date	12/08/2021	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI AD AVANTE (A)	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	KMHD841CMKU933924	Colour	BLACK	
Odometer	34901 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	WINDFORCE	7 mm	
L/H Front Tyre	195/65 R15	WINDFORCE	7 mm	
R/H Rear Tyre	195/65 R15	DUNLOP	7 mm	
L/H Rear Tyre	195/65 R15	DUNLOP	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/08/2021	Inspection Date	12/08/2021	
Survey held at	15 KAKI BUKIT ROAD 4 #01-05/53			
Repairer	ASIA MOTORSPORTS SOLUTION PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	