

A14.

輝 陽 汽 車 有 限 公 司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST & Reg No. 201629438M

28/07/2021

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR TOYOTA PRIUS HYBRID 1.8S A - SMG2733P

1pc	rear bumper	\$	928.35
1pc	rear bumper LH side retainer	\$	141.40
1pc	rear bumper diffuser	\$	379.00
1pc	rear bumper reinforcement	\$	458.00
1pc	rear bumper LH side lamp	\$	281.50
1pc	rear bumper LH side garnish	\$	381.80
1pc	rear bumper LH side inner shield	\$	285.50
		\$	2,855.55
less 25%		\$	713.89
		\$	2,141.66
wiring		\$	50.00
spray painting		\$	800.00
labour charges		\$	800.00
Total		\$	3,791.66

