



Pte Ltd

TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

Register number : 201015366H

REPAIR PERFORMA INVOICE

Vehicle number	SMK7280A
Make / Model	MITSUBISHI ATTRAGE
Chassis number	MMBSTA13AKH001400
Accident date	9/8/2021
Reference	2108-04

FCI

Qty Particulars

Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS		
1	FRONT BUMPER	687.20 <i>del</i>
2	FRONT BUMPER RETAINER	<i>LHX</i> 56.40 <i>RH</i> <i>del</i> 28.20
1	FRONT BUMPER FOG LAMP	189.60 <i>Eng</i>
1	FRONT BUMPER FOG LAMP COVER	89.20 <i>cut</i>
1	FRONT BUMPER FOG LAMP CHROME	138.50 <i>cut</i>
1	FRONT BUMPER INNER GARNISH	186.65 <i>X</i> <i>nn</i>
1	FRONT BUMPER REINFORCEMENT	350 387.90 <i>bt</i>
1	FRONT BUMPER LOWER GRILLE	168.00 <i>del</i>
1	FRONT GRILLE	322.80 <i>X</i>
1	FRONT GRILLE OUTER CHROME MOULDING	246.60 <i>X</i> <i>nn</i>
1	FRONT GRILLE EMLBEM	87.00 <i>X</i>
1	FRONT FENDER RH	438.90 <i>bt</i>
1	FRONT FENDER INNER SHIELD RH	181.40 <i>nn</i>
1	FRONT FENDER EMBLEM	59.00 <i>del</i>
1	FRONT FENDER INNER PANEL	469.90 <i>X</i> <i>nn</i>
1	FRONT FENDER BRACKET RH	52.25 <i>X</i> <i>nn</i>
1	WASHER TANK	89.20 <i>del</i>
1	HEADLAMP RH	510 576.00 <i>nn</i>
1	BONNET	722.00 <i>RY</i>
2	BONNET HINGE	183.00 <i>X</i> <i>nn</i>
1	FRONT LOWER ARM RH	268.00 <i>X</i> <i>nn</i>
1	FRONT SHOCK ABSORBER RH	344.70 <i>X</i> <i>nn</i>
1	FRONT KNUCKLE ARM RH	329 438.00 <i>X</i> <i>bt</i>
1	FRONT KNUCKLE ARM BEARING RH	282 389.60 <i>X</i> <i>bt</i>
		6771.80
Less 10%		677.18
Subtotal		6094.62
Balance C/F		3542.20
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
1 SET	FRONT BUMPER CLIP	30.00 <i>nn</i>
1 SET	FRONT FENDER INNER SHIELD CLIP	30.00 <i>del</i> 10
1	BRAKE FLUID	50.00 <i>X</i> <i>nn</i>
1	FRONT TYRE	250.00 <i>X</i> <i>nn</i>
1	FRONT RIM	400.00 <i>cut</i>
Subtotal		760.00
		440

S/No	LABOUR AND MISCELLANEOUS CHARGES	
1	CHECK FRONT WIRING AND LIGHTNING SYSTEM	60.00 30
2	COMPUTERISED AND CHECK WHEEL ALIGNMENT	200.00 80
3	REMOVE AND REPLACE FRONT UNDERCARRIAGE	200.00 100 ✓
7	PANEL BEATING ON AFFECTED AREAS	1200.00 400
8	SPRAY PAINTING ON AFFECTED AREAS	1200.00 500
9	APPLY ANTI RUST ON AFFECTED AREAS	150.00 30
	Subtotal	3010.00
	Grand total	9864.62

1140

Tanpin 97495749

'up' 12/8/21 @ 220 pm

1/3 Resurvey after repair

Tanpin @ 11/11/2021

04 days

3186.18

440

1140

4766.18

1/3 @ 3800

04 days

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
--