

SJE :

Date of Survey :

Date of ReSurvey:

Contacts :

After-Paint:

Vehicle Nos : **SLX 7441 X**

Made : Honda Civic

Year : 2018

Chassis No : MRHFC5650JT000379

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Bootlid	1	\$ 789.60	\$ 655.20	789.60 DD✓
2	Bootlid logo	1	\$ 69.50	\$ 40.00	69.50 } NEC✓
3	Bootlid emblem 'Civic'	1	\$ 98.00	\$ 48.00	98.00 }
4	Bootlid emblem 'i-vtec'	1	\$ 98.00	\$ 50.00	98.00 }
5	Bootlid lamp	2	\$ 255.00	\$ 510.00	972.60 BR✓
6	Bootlid inner lock	1	\$ 325.60	\$ 195.30	325.60 JM✓
7	Bootlid lock stricker	1	\$ 68.20	\$	68.20 NDX
8	Bootlid antenna sensor	1	\$ 364.20	\$ 180.00	364.20 BR✓
9	Bootlid inner trim board	1	\$ 204.60	\$	204.60 NDX
10	Bootlid weatherstrip	1	\$ 372.90	\$ 144.20	372.90 TN✓
11	Bootlid outer garnish	1	\$ 348.60	\$ 215.00	348.60 BR✓
12	Bootlid number plate lamp w/switch	1	\$ 155.30	\$	155.30 NDX
13	Bootlid reverse camera	1	\$ 488.00	\$	488.00 NDX
14	Bootlid hinge	2	\$ 152.00	\$	304.00 BTXR
15	Rear bumper	1	\$ 895.30	\$ 631.20	895.30 BR✓
16	Rear bumper lower	1	\$ 386.00	\$ 178.00	386.00 BR✓
17	Rear bumper side retainer	2	\$ 59.80	\$	✓119.60 NEC✓
18	Rear bumper reinforcement	1	\$ 190.80	\$	✓190.80 BT✓
19	Rear bumper bracket	2	\$ 66.00	\$	✓132.00 BR✓
20	Rear bumper reflector	2	\$ 125.40	\$	✓250.80 BR✓
21	Rear bumper reflector garnish	2	\$ 85.80	\$ 210.90	171.60 BR✓
22	Rear bumper reverse sensor	3	\$ 152.30	\$ 456.90	860.00 SC✓
23	Rear bumper reverse sensor wiring harness	1	\$ 298.00	\$ 252.30	298.00 Cut✓
24	Rear end panel	1	\$ 863.70	\$ 805.00	863.70 DD✓
25	Rear end panel top garnish	1	\$ 208.60	\$	✓208.60 BR✓
26	Spare tyre panel	1	\$ 736.90	\$ 619.60	736.90 DD✓
27	Spare tyre panel top board	1	\$ 195.80	\$	✓195.80 BR✓
28	Spare tyre tool tray	1	\$ 155.90	\$	155.90 NDX
29	Rear fender	2	\$ 968.10	\$	1,936.20 DDXR
30	Rear fender inner trim board	2	\$ 298.70	\$	✓597.40 TN✓
31	Rear windscreen moulding	1	\$ 198.00	\$	198.00 NNX
32	Rear chassis RH	1	\$ 758.00	\$ 668.70	758.00 BT✓
33	Taillamp	2	\$ 723.50	\$ 1447.00	1,684.60 BR✓
34	Taillamp base panel	2	\$ 289.70	\$	579.40 DD✓

Survey 12/8/2021
Resurvey 13/8/2021
Team Win Titim Win
1630hrs 1600hrs

Part by Part repair 20%
Repair days 12

Parts Sub Total : \$ 16,127.90
Discount : \$ 3,225.58
PARTS TOTAL : \$ 12,902.32

@20%
11,224.50
2,244.90
8,979.60

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	Sundries	1	\$ 80.00	\$ 80.00	NNX
2	Bootlid sealant	1	\$ 100.00	\$ 40.00 100.00	NECV
3	Bootlid lamp clips	2	\$ 50.00	\$ 100.00	NNX
4	Bootlid lamp seal	2	\$ 60.00	\$ 60.00 120.00	NECV
5	Bootlid inner trim board clips	1	\$ 50.00	\$ 20.00 50.00	NECV
6	Bootlid outer garnish clips	1	\$ 50.00	\$ 30.00 50.00	NECV
7	Rear bumper clips	1	\$ 50.00	\$ 30.00 50.00	NECV
8	Rear bumper lower clips	1	\$ 50.00	\$ 20.00 50.00	NECV
9	Rear bumper reflector garnish clips	2	\$ 50.00	\$ 100.00	NNX
10	Rear bumper reverse sensor seal	3 4	\$ 48.00	\$ 192.00	NECV
11	Rear end panel sealant	1	\$ 100.00	\$ 30.00 100.00	NECV
12	Rear end panel top garnish clips	1	\$ 50.00	\$ 20.00 50.00	NECV
13	Spare tyre panel sealant	1	\$ 100.00	\$ 30.00 100.00	NECV
14	Rear fender sealant	2	\$ 100.00	\$ 200.00	NNX
15	Rear fender inner trim board clips	2	\$ 50.00	\$ 40.00 100.00	NECV
16	Rear windscreen sealant	1	\$ 100.00	\$ 100.00	NNX
17	Rear windscreen inner seal	1	\$ 60.00	\$ 60.00	
18	Rear windscreen primer & cleaner	1	\$ 80.00	\$ 80.00	
19	Rear chassis sealant	1	\$ 100.00	\$ 30.00 100.00	NECV
20	Taillamp clips	2	\$ 50.00	\$ 20.00 100.00	NECV
21	Taillamp seal	2	\$ 60.00	\$ 60.00 120.00	NECV
22	Taillamp base panel sealant	2	\$ 100.00	\$ 30.00 200.00	NECV
23	Rear number plate w/casing	1	\$ 80.00	\$ 50.00 80.00	BRU
SPECIAL NETT TOTAL :				\$ 2,282.00	

702.00

Nos.	LABOUR	S\$	
1	R&R rear bootlid component	\$ 80.00 150.00	/
2	R&R rear bumper reverse sensor	\$ 60.00 100.00	/
3	R&R reverse camera	\$ 100.00	NNX
4	R&R rear windscreen	\$ 250.00	NNX
5	R&R rear exhaust pipe	\$ 70.00 150.00	/
6	Check wiring	\$ 30.00 100.00	/
7	Upholstery	\$ 300.00	NNX
8	Diagnostic & reset fault code	\$ 120.00 300.00	NECV
9	Panel beating	\$ 1400.00 2,000.00	/
10	Rust proofing	\$ 200.00	NNX
11	Spray Painting	\$ 1400.00 2,000.00	/
LABOUR TOTAL :		\$ 5,650.00	

3,160.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Prepared by: (8269-9999) Page 2 of 2

Date:

Parts 8979.60 PARTS TOTAL : \$ 12,902.32
 SN 702.00 SPECIAL NETT TOTAL : \$ 2,282.00
 Labour 3160.00 LABOUR TOTAL : \$ 5,650.00
 12841.60 GRAND TOTAL : \$ 20,834.32

COR \$12,841.00 on Part by Part basis