

ASS. REQ. BY:

REF:

AG/ 21008459/kb

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 49k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 11/22 Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGZ 83918 Yr Regn: 11, 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Toy Vias c.c. 1497

Colour: M. Black A/C: Insured / Std / NI / NA

Sp. Reading: 25739P T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR0531449.305031490

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD / Rlm or

Tyre Size: F: CST 185/80R15

R: Rspu

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 9 mm

L/Bal. 6 mm

L/Bal. 9 mm

D.O.A. 11/8/21

D.O.I. 12/8/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

13/8 11:30 @ 36000 Car Formed

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S - RS - SI

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$)

NGS AUTOMOTIVE

Blk 10 Ang Mo Kio Ind. Pk 2a #02-01 AMK AutoPoint Singapore 568047
Tel: 64815727 Fax: 64815772 Email: evelyn1911ngsautomotive@gmail.com
Reg No.: 53405718K

QUOTATION

No. : AQT-0042

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIMS DEPT
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

Your Ref. :
Our Ref : AQT-0042/SGZ8391
C. C. :
Date : 12-08-2021
Page : 1 of 2

TEL : 6419 3000

FAX :

Description	Qty	U/ Price S\$	Amount S\$
ACCIDENT ON 11/08/21 INVOLVING SGZ8391Z & SKX7444A ALONG CLEMENTI ROAD/WEST COAST HIGHWAY CLAIMS AGAINST SKX7444A (AIG) REPLACEMENT PART: TY VIOS NCP93			
REAR BOOT LID <i>589.10</i>	1	684.05	<i>R</i> 684.05 ✓
REAR BOOT HINGE RH/LH	2	49.70	<i>R</i> 99.40 X
BAR, REAR BOOT RH/LH	2	46.71	<i>R</i> 93.42 X
REAR BOOT INNER LOCK	1	126.28	<i>Dir</i> 126.28 ✓
REAR BUMPER <i>451.60</i>	1	496.04	<i>R</i> 496.04 ✓
REAR BUMPER RETAINER UPPER RH/LH	2	<i>MS Dir</i> 42.50	85.00 ✓
REAR BUMPER RETAINER LOWER RH/LH	2	<i>MS Dir</i> 105.50	211.00 ✓
REAR BUMPER SEAL RH/LH	2	53.00	<i>NSP</i> 106.00 X
REAR BUMPER LOWER REFLECTOR RH/LH	2	<i>MS Dir</i> 94.31	188.62 ✓
REAR END PANEL <i>575</i>	1	592.22	<i>R</i> 592.22 ✓
REAR END PANEL GARNISH	1	226.83	<i>Dir</i> 226.83 ✓
LUGGAGE COMPARTMENT PANEL	1	639.50	<i>R</i> 639.50 X
CARRIER ASSY, SPARE WHEEL	1	65.34	<i>SL</i> 65.34 X
LUGGAGE COMPARTMENT BOARD	1	175.91	<i>SL</i> 175.91 X
COVER, ROOM PARTITION	1	203.00	<i>SL</i> 203.00 X
BOARD, ROOM PARTITION LH	1	154.50	<i>SL</i> 154.50 X
WEATHERSTRIP, TRUNK	1	<i>Dir TRA</i> 137.42	137.42 <i>50</i> ✓
STRIKER, LUGGAGE COMPARTMENT	1	23.00	<i>R</i> 23.00 X
TAILLAMP RH/LH	2	<i>MS CR</i> 243.20	486.40 ✓
TAILLAMP GASKET RH/LH	2	39.46	<i>M</i> 78.92 ✓
TAILLAMP LOWER PANEL EXTENSION LH	1	135.00	<i>R</i> 135.00 ✓
REAR FENDER LH	1	1,011.00	<i>R</i> 1,011.00 X

*Not Authorised
U/ Dir @ 3600h
Recovery After Rain
6 days*

*OK
12-08-21*

NGS AUTOMOTIVE

Blk 10 Ang Mo Kio Ind. Pk 2a #02-01 AMK AutoPoint Singapore 568047
Tel: 64815727 Fax: 64815772 Email: evelyn1911ngsautomotive@gmail.com
Reg No.: 53405718K

QUOTATION

No. : AQT-0042

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIMS DEPT
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

Your Ref. :
Our Ref : AQT-0042/SGZ8391
C. C. :
Date : 12-08-2021
Page : 2 of 2

TEL : 6419 3000

FAX :

Description	Qty	U/ Price S\$	Amount S\$
SPARE TYRE BOLT	1	162.73	162.73 X
REAR BOOT 'BADGE'	1	47.53	47.53 —
EMBLEM 'G'	1	44.52	44.52 —
EMBLEM 'VIOS'	1	54.80	54.80 —
SubTotal			6,328.43
Less 25%	1	-1,582.10	-1,582.10
CLIPS, LUGGAGE COMPARTMENT TRIM S.NETT	16	5.00	80.00 X
CLIPS, TAILLAMP, TOP/BOT RH/LH S.NETT	2	8.50	17.00 4
REAR NO PLATE C/W CASING S.NETT	1	50.00	50.00 X
PARKING SENSOR S.NETT	1	280.00	280.00
TO REMOVE REAR DAMAGED PART WITH ALL NECESSARY COMPONENT/ATTACHMENT. STRAIGHTEN CHASSIS MEMBER, REPAIR/RESHAPE DENTED BODY PANEL. REPLACE DAMAGED PART. REFIT INTO POSITION.	1	1,600.00	1,600.00
TO SPRAY REAR PORTION	1	1,400.00	1,400.00
TO TRANSFER RR BOOT MECHANISM	1	150.00	150.00
CHECK WIRING & LIGHT FUNCTION	1	50.00	50.00

Any other parts which necessitate repair or renewal will incur additional charged.
Please contact our Ms Evelyn @ HP 96955547 to arrange for survey. Thank you.

Yours faithfully,



EVELYN

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total 8,390.33

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	077C

Vehicle Details

Vehicle No.:	SGZ8391Z
Vehicle to be Exported:	Yes
Intended Deregistration Date:	13 Aug 2021
Vehicle Make:	TOYOTA
Vehicle Model:	VIOSE AUTO
Primary Colour:	Black
Manufacturing Year:	2007
Engine No.:	1NZX634481
Chassis No.:	MR053HY9305031490
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,466.00
Original Registration Date:	20 Nov 2007
First Registration Date:	20 Nov 2007
Transfer Count:	2
Actual ARF Paid:	\$13,713.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	19 Nov 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$20,997.00
COE Rebate Amount:	\$5,319.00
Total Rebate Amount:	\$5,319.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 12 Aug 2021

OK