

Estimation

Date
Vehicle SFL 1199 U
Make/Model HYUNDAI AVANTE
Chassis No. KMHLN41ETMU067337

No.	Description	Unit	Unit Price	Amount
	Parts Replacment			
1	BONNET <i>Ry</i>	1	\$	-
2	FRONT GRILLE <i>cm</i>	1	\$	-
3	FRONT LOGO - HYUNDAI <i>net</i>	1	\$	-
4	HEADLAMP L+R <i>LHX RH m</i>	2	\$	-
5	HEADLAMP BRACKET L+R <i>LHX RH m</i>	2	\$	-
6	FRONT BUMPER <i>de</i>	1	\$	-
7	FRONT BUMPER CENTER GARNISH <i>x</i>	1	\$	-
8	FRONT BUMPER SIDE GARNISH L+R <i>LHX RH X</i>	2	\$	-
9	FRONT BUMPER FOG LAMP L+R <i>LHX RH X</i>	2	\$	-
10	FRONT BUMPER FOG LAMP GARNISH L+R <i>LHX RH m</i>	2	\$	-
11	FRONT BUMPER RETAINER L+R <i>LHX RH m</i>	2	\$	-
12	FRONT BUMPER REINFORCEMENT BAR <i>ht</i>	1	\$	-
13	FRONT BUMPER LOWER BEAM <i>ht</i>	1	\$	-
14	FRONT BUMPER SPONGE <i>cm</i>	1	\$	-
15	FRONT BUMPER UNDERCOVER <i>fm</i>	1	\$	-
16	FRONT FENDER COWLING L+R <i>LHX RH m</i>	2	\$	-
17	FRONT SUPPORT PANEL <i>cm</i>	1	\$	-
18	FRONT SUPPORT PANEL TOP GARNISH <i>cm</i>	1	\$	-
19	FRONT BRAKE ASSIST SENSOR <i>x</i>	1	\$	-
20	AIRCON CONDENSOR <i>x</i>	1	\$	-
21	AIRCON CONDENSOR AIR GUIDE L+R <i>x</i>	2	\$	-
22	RADIATOR <i>x</i>	1	\$	-
23	RADIATOR COWLING <i>x</i>	1	\$	-
24	FRONT HORN <i>x</i>	1	\$	-
	Front Top Air Duct <i>cm</i>		Total	\$ -
			Less 20%	\$ -
			Total	\$ -

	S/Nett Items				
1	BONNET INSULATOR CLIPS	1	100	\$ 50	100.00
2	FRONT BUMPER CLIPS	1	100	\$ 30	100.00
3	FRONT NUMBER PLATE	1	120	\$ X	120.00
4	FRONT FENDER COWLING CLIPS	1	100	\$ 10	100.00
5	FRONT SUPPORT PANEL TOP GARNISH CLIPS	1	100	\$ 20	100.00
			Total	\$	520.00

	LABOUR					
1	PANEL BEATING ON AFFECTED AREAS	1	1200	\$ 600	1,200.00	
2	SPRAY PAINT ON AFFECTED AREAS	1	1000	\$ 500	1,000.00	
3	TO CHECK WIRING AND HEADLAMP FOCUS	1	150	\$ 30	150.00	
4	TO CHECK WIRING AND FOG LAMP FUNCTION	1	150	\$ X	150.00	
5	TO RNR INNER TRIM AND UPOLSTERY	1	400	\$ X	400.00	
6	TO CHECK WATER LEAK	1	150	\$ X	150.00	
7	TO RNR FRONT AIR CON CONDENSOR AND TOP UP GAS	1	300	\$ 100?	300.00	
8	TO RNR FRONT RADIATOR	1	250	\$ X	250.00	
9	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	1	600	\$ X	600.00	
10	TO RNR FRONT PARKING SENSOR AND CHECK FUNCTION	1	150	\$ X	150.00	
11	TO PERFORM RUST PROOFING	1	400	\$ X	400.00	
12	TO RNR HORN AND TEST FUNCTION	1	150	\$ X	150.00	
				Total Labour	\$ 4,900.00	
				Parts Replacement Amount	\$ 520.00	
				Total Amount	\$ 5,420.00	

Tanpiah 9749 5749
 WP 12/8/21 @ 430
 1/5 Resurvey after repair
 Tanpiah C/Handover
 5 days

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	591D
Vehicle Details	
Vehicle No.:	SFL1199U
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Aug 2021
Vehicle Make:	HYUNDAI
Vehicle Model:	CN7 AVANTE 1.6 DOHC CVT S
Primary Colour:	Grey
Manufacturing Year:	2020
Engine No.:	G4FMLU173755
Chassis No.:	KMHLN41ETMU067377
Maximum Power Output:	90.2 kW (120 bhp)
Open Market Value:	\$18,875.00
Original Registration Date:	21 Nov 2020
First Registration Date:	21 Nov 2020
Transfer Count:	0
Actual ARF Paid:	\$8,875.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Nov 2030
PARF Rebate Amount:	\$6,656.00
Intended COE Rebate Details	
COE Expiry Date:	20 Nov 2030
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$37,690.00
COE Rebate Amount:	\$34,758.00
Total Rebate Amount:	\$41,414.00

The information contained herein is correct as at 10 Aug 2021

OK