

ASS. REC. BY:

REF: CS/

C22 / 21008474 / Kuc

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLL 3551B

at Workshop m/s KICIM 141N

of \_\_\_\_\_

Insured: SJF 914M

Policy No. DMPCSNW00163332000

Claims No. SNM21D204429/C02


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLL 3551B Yr Regn: 02, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or 1498

Make: Honda Jazz C.C. 1498

Colour: M. Silver A/C: Insured / Std / NI / NA

Sp. Reading: 139812 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JHM GK 575014 X 202 394

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / STD A/Rlm or

Tyre Size: F: 185/55R16

R: \_\_\_\_\_

BS / JUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front Rear

R/Bal. 3 mm R/Bal. 3 mm

L/Bal. 3 mm L/Bal. 3 mm

D.O.A. 10/8/21 D.O.I. 13/8/2021

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

13/8 Simon said 1-B.1, Got B.I.

16/8/2021 Revise to CTI via Merimen.

Confirm P/P \$4199.39, 5 repair days.

(RED \$1161.89; 22%)

Date/Time, File Pass to?

☐: Prell. Report

1) 5/11 TYPIST

☐: Final Report

Date/Time, File Return to?

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Add Fee: ☐: Site Insp (\$)☐: Interview (\$)☐: Tech Invs (\$)☐: Weekend (\$)

Report Format: TP

Lump Sum / I.B.I: (\$ 4199.39



## 金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,  
Sin Ming AutoCity, Singapore 575722  
Tel: 6452 7018 Fax: 6458 3895  
Email: service@kkimhin.com.sg

No. : 31958

Vehicle Insured : SJF 914 M  
Accident Date : 10-Aug-2021

*NOT Notified*

Date : 12-Aug-2021

Our Ref : 021323 (CHINA) / QUEK

*11 Rmp @ 1.16/1*

PAGE : 1

BUKIT BATOK DRIVING CENTER LTD  
Singapore

*Money After Paim*

*5 days*

### ESTIMATED COST OF REPAIR FOR HONDA JAZZ 1.5 VTIR M/T ABS(2017) SLL3551B

1 pc rear bumper		<i>B</i>	492.00	✓
2 pcs rear bumper side retainer (LH/RH)	@ S\$ 30.00	<i>old ori</i>	60.00	<i>Lt</i>
2 pcs rear bumper side lower garnish (LH/RH)	@ S\$ 45.00	<i>sn</i>	90.00	X
10 pcs rear bumper clips	@ S\$ 3.90	<i>me</i>	39.00	✓
1 pc rear end panel		<i>B</i>	352.20	✓
1 pc rear end panel top garnish		<i>ori</i>	100.00	✓
1 pc o/s tail lamp		<i>ori</i>	237.00	✓
1 pc spare tyre sponge compartment		<i>CM</i>	680.00	✓
1 pc tailgate		<i>B</i>	769.30	✓
1 pc tailgate weatherstrip		<i>ori</i>	122.30	<i>50% sn</i>
1 pc tailgate lock			280.00	?
1 pc tailgate "JAZZ" emblem		<i>me</i>	38.00	✓
1 pc tailgate outer chrome		<i>sn</i>	195.60	X
1 pc tailgate inner trimboard			189.80	?
1 pc tailgate glass moulding		<i>me</i>	150.00	✓
1 pc tailgate inner handle pocket		<i>ori</i>	63.40	✓
			3,858.60	
	Less 20% :		-771.72	
			3,086.88	

1 pc rear bumper "L" plate bracket		<i>ori</i>	60.00	sn	X
2 pcs tailgate "8" & "0" reflective sticker	@ S\$ 10.00	<i>me</i>	20.00	sn	✓
1 pc tailgate "THANK YOU FOR YOUR PATIENCE"		<i>me</i>	150.00	sn	✓
1 pc tailgate glass sealant		<i>me</i>	40.00	sn	✓
1 pc tailgate glass damping seal		<i>me</i>	20.00	sn	✓

#### LKK Auto Consultants hence notify

#### the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Con't Page 2 ...

Acknowledged by Repairer

Signature:



CO. REG. NO: 199402370D  
GST NO: M2-0123250-3

AUTO PTE LTD

## 金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,  
Sin Ming AutoCity, Singapore 575722  
Tel: 6452 7018 Fax: 6458 3895  
Email: service@kkinhin.com.sg

Vehicle Insured : SJF 914 M  
Our Ref : 021323

Page : 2  
No. : 31958

To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.	6001 680.00
To remove and renew rear windscreen glass and conduct water leak test.	120.00 ✓
To remove and refit rear upholstery trimming, roof lining, seats, speaker board in order to facilitate repairing works	180.00 601
To apply undersealing	80.00 601
To transfer tailgate's fittings	80.00 601
To putty and respray on affected portions.	780.00 601
To focus taillamps. To check rear wiring and lighting operation.	30.00 201
Total :	----- S\$ 5,326.88 =====

Singapore Dollars Five Thousand Three Hundred  
and Twenty Six and Cents Eighty Eight Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.



# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission ..... 11/08/2021 18:35 (SGT)  
Date of Accident ..... 10/08/2021 14:37 (SGT)  
Exact Location of Accident ..... Choa Chu Kang, Singapore  
Additional Location Information ..... CHOA CHU KANG AVENUE 6 , FILTER LANE TO BRICKLAND ROAD  
Country/State of Loss ..... Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SLL3551B

### INSURED/POLICYHOLDER

Is company? ..... Yes  
Name Of Registered Owner ..... BUKIT BATOK DRIVING CENTRE LTD  
Company Reg No ..... 1XXXXX155R  
Email Address ..... TANBOONKIAT@BBDC.SG  
Mobile Phone No ..... (Phone) +65-65943515  
Alternative Phone No ..... (Office) +65-65943515

### VEHICLE PARTICULARS

Manufacturer ..... Honda  
Model ..... Jazz  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... -  
Are you claiming under your own insurance policy for repair to your vehicle? ..... No - Claiming third party  
Vehicle Category ..... Commercial vehicle  
Transmission ..... Manual  
CC ..... 1498

### INSURANCE COMPANY

Name of Insurance Company ..... NTUC Income Insurance Co-operative Ltd  
Type of Coverage ..... Comprehensive  
Fleet Policy ..... Yes  
Policy Number ..... 5114124556-01-000046  
Cover Note Number ..... -

### DRIVER

Name of Driver ..... NG SHU YI



## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.  
(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

BUKIT BATOK DRIVING CENTRE LTD  
815, BUKIT BATOK WEST AVENUE 5  
SINGAPORE 658083  
TEL: 6561 1233 FAX: 6561 0777


Policyholder's Signature / Date & Time

Signature 10/2/21  
Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

### Sketch Plan







# SINGAPORE POLICE FORCE



T/20210811/2067

Police Station Of Origin:  
Yishun North N.P.C  
31 Yishun Central SINGAPORE 768327  
Tel No: 1800-8529999

1 of 4

Report No. T/20210811/2067

## REPORT OF A TRAFFIC ACCIDENT

Data/Time Report Made: 11/08/2021 15:02		Vide Report No.:		Station Diary No.: 71	
<b>Informant's Particulars</b>					
Name of Informant: LEE CHAY KIAN			Address: APT BLK 411 ANG MO KIO AVENUE 10 #12-869 SINGAPORE 560411		
ID Type / ID No.: NRIC NO / S1621448E			Contact No.: Home/Office: Mobile: 94898171		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 58	Date of Birth: 10/08/1963	Type of Informant: Driving Instructor		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Driving instructor/teacher			Driving Licence Information: Class: Date of Expiry:		

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 10/08/2021 14:40	Type of Location: Filter Lane
Location: CHOA CHU KANG AVENUE 6				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

				Color	Condition	No. of Passenger
BJF914M	Car	HONDA		Black	Slightly Damaged	2
BJL3651B	Car	HONDA		Silver	Seriously Damaged	1

Any Pedestrian Involved: No		Use of Pedestrian Crossing: NA	
No. of Pedestrians Injured: NIL			





# SINGAPORE POLICE FORCE



T/20210811/2067

2 of 4

Police Station Of Origin:  
Yishun North N.P.C  
31 Yishun Central SINGAPORE 768827  
Tel No: 1800-8529999

Report No. T/20210811/2067

## CONTINUATION OF REPORT

Name	LEE CHAY KIAN		ID No.	S1621448E
Related Vehicle	SLL3551B (Car)		Contact No.	94898171
Hospital/Clinic	KHOO TECK PUAT HOSPITAL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	11/08/2021		Date Discharge	11/08/2021
No. of Days granted Medical Leave	04	Degree of Injury	Slight	
Name	NG SHU YI		ID No.	T0200230I
Related Vehicle	SLL3551B (Car)		Contact No.	88233011
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	

### Brief Details.

On 10/08/2021 at about 1437hrs, my student driver namely, Ng Shu Yi T0200230I Tel: 88233011 was exiting Choa Chu Kang Avenue 6 exit towards Brickland Road. Whilst inside the filter lane to exit Brickland Road, suddenly I felt a great impact on the rear of my company vehicle SLL3551B (BBDC, Honda Jazz Silver). The impact was so great that I was forced forward but hit the back parts of my body onto the seat due to the recall effect caused by the force. After the collision, I checked with my learner driver, Ng Shu Yi and she informed me that she was fine.

We then alighted my company vehicle and approached a female driver, (Chinese in her 30s) who claimed to be the driver of vehicle SJF914M (Black Honda) that have collided onto the rear of my company vehicle. She have 2 passengers which was her husband and their child (about 4-5 years old). We took photographs at scene and agreed to claim through insurance. Nobody was injured at scene. However, the rear door of my company vehicle SLL3551B was badly damaged due to the great impact caused by vehicle SJF914M. The front bumper of SJF914M was slightly damaged due to the collision. We did not exchange particulars at the scene and I drove the said company vehicle back to Bukit Batok Driving Centre where my superior assessed the damages on my vehicle.

Later that same day, at about 4-5pm, when I reached home, I already started feeling some pain on my back due to the accident. The following day (11/08/2021), I consulted medical attention at Khoo Teck Puat Hospital A&E and was given 4 days of medical leaves dated 11/8/21 to 14/8/21.