



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD 4 SHENTON WAY #21-01,SGX CENTRE 2 SINGAPORE 068807		Ref: CS/MSG21008476/Buf3 Date: 12/08/2021 Code: MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YP 4091E	Veh. Inspected	SJN 6981L
Policy No.	29075764MKF	Coverage (\$)	0.00
Claim No.	637490	Excess (\$)	0.00
Assign From	MERIMEN (KATHERINE WONG)	Assign Date	12/08/2021
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	12/08/2021	Inspection Date	13/08/2021
Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			