



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
NTUC INCOME INSURANCE CO-OPERATIVE LTD 73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556 ATTN: RAJESWARY		Ref: CS3/INC21002426/Gqf3e2-1 Date: 30/08/2021 Code: INC	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJE 1667A	Veh. Inspected	SLK 3287U
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1121607-003	Excess (\$)	0.00
Assign From	RAJESWARY	Assign Date	26/07/2021
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ C 180	c.c	1796
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WDD2040452A595897	Colour	WHITE
Odometer	210267 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	245/40ZR18	FALKEN	6 mm
L/H Front Tyre	245/40ZR18	FALKEN	6 mm
R/H Rear Tyre	245/40ZR18	FALKEN	6 mm
L/H Rear Tyre	245/40ZR18	FALKEN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	18/02/2021	Inspection Date	23/02/2021
Survey held at	GARAGE 13 PTE LTD 8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	