

## Mei Kwan (LKKAuto)

---

**From:** Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>  
**Sent:** Wednesday, August 11, 2021 8:52 PM  
**To:** xin hua  
**Cc:** Lim, Kok-Chong; Abu Kassim, Noor Mariesa; Hor, Yinrul; Teo, Ericweihong  
**Subject:** aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBB6971Z AND SLQ5095L ON 20/07/2021  
**Attachments:** 11082021141917.pdf

### Without Prejudice

Your Reference: SLQ5095L  
Our Reference : GBB6971Z

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
You Jin Feng	Formteam Adjusters Pte Ltd
Li Lewei	Formteam Adjusters Pte Ltd
Henry Ng	Formteam Adjusters Pte Ltd
Kenji Tan	Formteam Adjusters Pte Ltd
Terrence Low	Formteam Adjusters Pte Ltd
Steve Chen Tsue Yee	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

**Divyashni Subramaniam**

**AIG**

FNOL Adjuster I

Auto Claims | AIG Asia Pacific Insurance Pte. Ltd.

Tel: 8001206556 | Ext: 1012103

[Divyashni.Subramaniam@aig.com](mailto:Divyashni.Subramaniam@aig.com) | [www.aig.sg](http://www.aig.sg)

---

**From:** xin hua <[xinhuaworkshop2@gmail.com](mailto:xinhuaworkshop2@gmail.com)>

**Sent:** Wednesday, August 11, 2021 2:22 PM

**To:** Abu Kassim, Noor Mariesa <[NoorMariesa.AbuKassim@aig.com](mailto:NoorMariesa.AbuKassim@aig.com)>; Lim, Sheng Yang <[ShengYang.Lim@aig.com](mailto:ShengYang.Lim@aig.com)>; Hor, Yinrul <[Yinrul.Hor@aig.com](mailto:Yinrul.Hor@aig.com)>

**Subject:** [EXTERNAL] PRI | Accident involving our client SLQ5095L and your insured GBB6971Z (AIG INS) | DOA-20/07/2021

This message is from an external sender; be cautious with links and attachments.

Greetings,

We are instructed by **Movesafe** to notify you of a road traffic accident on **20/07/2021** at about **14:16 hours** at **BLK 115 Marsiling Rise (Carpark No: WLW18)** involving our client's/customer's vehicle registration number **SLQ5095L** and vehicle registration number **GBB6971Z** driven by your insured at the material time.

A copy of the Singapore Accident Statement is enclosed for your kind attention.

As a result of the accident, our client's/customer's vehicle has been damaged. Before our client/we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insured would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client/we shall proceed to repair the vehicle without further reference to you.

Kindly note the vehicle SLQ5095L has yet in our workshop and we will inform you in advance once the vehicle is ready for pre-inspection.

We look forward to having a direct settlement and please provide us with the named survey companies to **be appointed as the single joint expert** as finalization/processing of the claims after finalization are done promptly.

Thank You.

Regards,

Irene

HP : 9151 6861

Xin Hua Workshop Pte. Ltd.

8 Kaki Bukit Avenue 4

#08-09

Premier @ Kaki Bukit

Singapore 415875