



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
NTUC INCOME INSURANCE CO-OPERATIVE LTD 73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556 ATTN: AZHARI			Ref: CS3/INC21005484/Uuf3e2-1 Date: 16/08/2021 Code: INC	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLN 9841P	Veh. Inspected	SKP 1791D	
Policy No.		Coverage (\$)	0.00	
Claim No.	MT/1130386-002	Excess (\$)	0.00	
Assign From	INCOME	Assign Date	13/08/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS ALPHA HYBRID (A)	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	ZVW400009083	Colour	WHITE	
Odometer	551829 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	FIRENZA	6 mm	
L/H Front Tyre	215/60 R16	FIRENZA	6 mm	
R/H Rear Tyre	215/60 R16	FIRENZA	6 mm	
L/H Rear Tyre	215/60 R16	FIRENZA	6 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	03/05/2021	Inspection Date	05/05/2021	
Survey held at	FEI AUTO 25 KAKI BUKIT ROAD 4, #03-33, SYNERGY @ KB, SINGAPORE 417800			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	