

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	BONNIE KWOK LL	.C	Ref:	CS/LAW21008499/Uuf3e2	
	101A UPPER CRC #08-12 PEOPLE'S SINGAPORE 0583	PARK CENTRE	Date:	21/10/2021	
			Code:	L094	
1.	. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
	Insured Veh.	SHC 6191G	Veh. Inspected	SMP 1911B	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	BK.19771.20.P	Excess (\$)	0.00	
	Assign From	TEO WENG KIE	Assign Date	02/08/2021	
2. Vehicle Particulars & Condition					
	Make & Model	MASERATI GRANTURISMO CAMBIOCORSA (A)	c.c	4691	
	Engine No.	HIDDEN	Year of Reg.	2010	
	Chassis No.	ZAMHH45C000053548	Colour	GREY / BLACK	
	Odometer	107114 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	245/35Z R20	TOURADOR	7 mm	
	L/H Front Tyre	245/35Z R20	TOURADOR	7 mm	
	R/H Rear Tyre	285/30 R20	BRIDGESTONE	7 mm	
	L/H Rear Tyre	285/30 R20	BRIDGESTONE	7 mm	
4.	Description of Damages				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
	REPAIR CONDITION SEE DETAILS.				
5.	General Information				
	Accident Date	17/02/2020	Inspection Date	01/09/2021	
	Survey held at	Block 5 Defu Lane 10, #01-582			
	Repairer	HENG MOTOR SERVICES			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				