

FormTeam Consultancy Pte Ltd

No.33, Ubi Ave 3
#02-15, Vertex
Singapore 408868

Tel : (65) 6509 1788
Fax : (65) 6509 6221

Email: motorsurvey@fta.com.sg

Co.Reg No: 200819280D

GST Reg No: 200819280D

Our Reference : NTUC20-020993/PRS/BT/ADJ/BT/ec

Your Reference: MT/1084820-002

Date : 02-Jun-2020

Motor Claims Department
NTUC Income Insurance Co-operative Limited
73 Bras Basah Road
#05-01 NTUC Trade Union House
Singapore 189556

Attention : Mr Marcus Xiao

Dear Sir/Mdm,

SURVEY OF VEHICLE NO. SMP 1911B

Pursuant to your instruction on 14-May-2020.

We recommend a repair cost of **\$10,750.00** (see report) based on lump sum repair and the estimated duration of repairs would take **05 days**.

We also enclosed our note of charges for your consideration.

Thank you for this assignment.

Your faithfully

FormTeam Consultancy Pte Ltd
Adjusters & Surveyors (Licensed Appraiser)



Bryan Teng
Automobile Appraiser

(Email : bryan@fta.com.sg)

Encl. Survey Report

FormTeam Consultancy Pte Ltd

AUTOMOBILE ASSESSMENT REPORT

Page No. 1

Our Reference : NTUC20-020993/PRS/BT/ADJ/BT/ec

Your Reference: MT/1084820-002

Date : 02-Jun-2020

Attention : Mr Marcus Xiao

TO : Motor Claims Department
NTUC Income Insurance Co-operative Limited
73 Bras Basah Road
#05-01 NTUC Trade Union House
Singapore 189556

Assessment of Vehicle No : **SMP 1911B**
Date of Accident : **17-February-2020**
Date of Inspection : **21-February-2020**
Address of Inspection : **5 Defu Lane 10 #01-582 S'539186**

We have carried out a physical assessment of **SMP 1911B** at **M/S Heng Motor Services Pte Ltd** according to your instructions on **20-Feb-2020**, dismantled items on **24-Feb-2020**, post repair survey on **13-Mar-2020** and are pleased to submit our report herewith.

1. VEHICLE PARTICULARS

Registration No. : SMP 1911B
Make & Model : Maserati Granturismo
Year of Registration : 2010
Engine Capacity : 4691 cc
Chassis No. : ZAMHH45C000053548
Engine No. : M145161396
Colour : Black
Mileage (km) : 76166

2. VEHICLE CONDITION

Body Paint : Good
Steering : Serviceable
Foot Brake : Serviceable
Parking Brake : Serviceable

3. TYRE PARTICULARS & CONDITION

Front

RH Make/Size : Michelin 245/35 R20 - 70%
LH Make/Size : Michelin 245/35 R20 - 70%

Rear

RH Make/Size : Michelin 285/35 R20 - 70%
LH Make/Size : Michelin 285/35 R20 - 70%

Note : % denotes the remaining percentage of the tyre


FormTeam Consultancy Pte Ltd

Our Reference : NTUC20-020993/PRS/BT/ADJ/BT/ec
Your Reference : MT/1084820-002
Vehicle Number : SMP 1911B

Page No. 2

4. DESCRIPTION OF DAMAGE

At the time of inspection, this vehicle sustained damages to the **N/S Front** portion. Please see attached scheduled for details.



5. REMARKS

Market Value : \$ **152,800.00**
Salvage Value : \$ **99,700.00**
Repair Limit (Nett Loss) : \$ **53,100.00**
Repairer's estimate : **Not Provided**
Nett Saving : -
Excess : -
Sum Insured : -
Our adjusted amount : \$ **10,750.00**
Estimated Repair Days : **05 days**

Additional photographs will be submitted upon request by our principal.

Pursuant to your instruction, we have **NOT AUTHORIZED** repair.

The assessment was conducted on a "**Without Prejudice**" basis.

If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by

FormTeam Consultancy Pte Ltd for any reliance on this report by any third party, unless with the permission of the addressee.

FormTeam Consultancy Pte Ltd

Our Reference : NTUC20-020993/PRS/BT/ADJ/BT/ec

Your Reference : MT/1084820-002

Vehicle Number : SMP 1911B

Page No. 3

[illegible]

FormTeam Consultancy Pte Ltd

Our Reference : NTUC20-020993/PRS/BT/ADJ/BT/ec
Your Reference : MT/1084820-002
Vehicle Number : SMP 1911B

Page No. 4

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	LABOUR		
1	Spray rust coating on the replaced & repaired panels.	-	-
2	To rewire front portion and refocus headlamp beam.	-	40.00
3	To remove, refix front undercarriage.	-	200.00
4	To remove, panel beating, welding, align and renew replaced parts.	-	600.00
5	To putty and respray painting on affected areas.	-	500.00
6	To conduct computerise wheel alignment test.	-	120.00
	Labour Total :	-	1,460.00
	TOTAL (PARTS & LABOUR) :	-	13,430.71

The final adjusted Lump Sum contract amount is **\$10,750.00**
(SINGAPORE DOLLARS TEN THOUSAND SEVEN HUNDRED AND FIFTY ONLY)

Frankie Pang
AMSAE(AUST), AMIRTE, AMSOE,
MASPACI, MSAAA
Licensed Appraiser

Bryan Teng
Automobile Appraiser

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2461
Vehicle Details	
Vehicle No.:	SMP1911B
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Mar 2020
Vehicle Make:	MASERATI
Vehicle Model:	GRANTURISMO CAMBIOCORSA
Primary Colour:	Grey
Manufacturing Year:	2010
Engine No.:	M145161396
Chassis No.:	ZAMHH45C000053548
Maximum Power Output:	323.0 kW (433 bhp)
Open Market Value:	\$127,289.00
Original Registration Date:	23 Jul 2010
First Registration Date:	23 Jul 2010
Transfer Count:	5
Actual ARF Paid:	\$127,289.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Jul 2020
PARF Rebate Amount:	\$63,644.00
Intended COE Rebate Details	
COE Expiry Date:	31 Oct 2029
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$37,502.00
COE Rebate Amount:	\$36,120.00
Total Rebate Amount:	\$99,764.00

The information contained herein is correct as at 13 Mar 2020

OK

FormTeam Consultancy Pte Ltd

Vehicle No: SMP 1911B

Workshop: Heng Motor Services Pte Ltd

Accident Date: 17 February 2020

No. 33 Ubi Ave 3
#02-15 Vertex
Singapore 408868

Tel : (65) 6509 1788
Fax : (65) 6509 6221

Email: motorsurvey@fta.com.sg
www.fta.com.sg

Co. Reg No: 200819280D

GST Reg. No: 200819280D













