Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd. 8 Temasek Boulevard #04-01 Suntec Tower Three Singapore 038988

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

From: LKK Auto Consultants Pte Ltd

Attn: Date: 16 Nov 2021

Preliminary Advice

Insured Vehicle No : YN2662G

 TP Vehicle No
 : GBF7005K
 Accident Date
 : 06/08/2021

 Make
 : NISSAN NV200
 Assignment Date
 : 13/08/2021

Date of Inspection : 12/08/2021 Est. Duration of Repair : 4

Inspection At : BEST SOLUTION AUTOCARE PTE LTD (HQ)

53 UBI AVE 1 #03-01 PAYA UBI INDUSTRIAL PARK

SINGAPORE 408934

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,832.00
Revised Amount	:S\$	2,744.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,744.50
Lump Sum Repair	:S\$	2,200.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly
		let us have your authorisation.

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments :Please note that the preliminary advice amount (Revised) stated are subject to consistency check, part prices and labour cost.