

The Motor Claims Department

M/s Lonpac Insurance Bhd

100 Beach Road #19-00 Shaw Tower Singapore 189702 File No:

SH/2021/143/08/005/od

Date

13-August-2021

Estimated cost of repair for vehicle no: GBC338L T

38L Toyota Town Ace

Policy no: Z21VC05007458 **Accident Date:** 6/8/2021 **Cost Price** Description Quantity 1 \$ 350.00 Bonnet 1 \$ RH Bonnet hinge 55.00 1 55.00 LH Bonnet hinge \$ \$ 80.00 Bonnet lock \$ 80.00 Bonnet emblem \$ RH head lamp 720.00 \$ LH head lamp 720.00 \$ Front bumper 680.00 \$ 28.00 Front bumper clips (1 set) \$ LH Front bumper retainer 55.00 \$ Front bumper tow cover 45.00 \$ LH front fender 350.00 LH front fender wheel cowling \$ 190.00 LH front fender wheel cowling clips (1 set) \$ 18.00 \$ LH front door 2,200.00 \$ 70.00 LH front door hinge top \$ 70.00 LH front door hinge lower \$ LH front door check 95.00 \$ 420.00 LH front door inner trim board \$ LH front door window regulator 280.00 \$ 1,200.00 Front support panel \$ 90.00 Bonnet lock centre bracket \$ 880.00 Air con condensor \$ 1 380.00 Air con condensor pipe inlet \$ 360.00 Air con condensor pipe outlet \$ Air con condensor fan motor 450.00 \$ Air con condensor fan blade 180.00 \$ Air con condensor fan cowling 250.00 \$ Radiator 780.00 \$ Radiator top hose 70.00 \$ Radiator fan motor 450,00 Radiator fan blade \$ 180.00 Radiator fan cowling \$ 250.00 LH front wheel house panel \$ 680.00 LH front wheel house-chassis member closing panel 380.00 \$ LH front door hinge pillar 1 450.00



LH front door frame complete pillar?	\$	380.00
Firewall panel	\$	1,800.00
Wiper panel 1	\$	580.00
Wiper panel garnish	\$	280.00
LH front wiper arm	\$	110.00
Front wiper linkage	\$	280.00
Front wiper motor	\$	480.00
Front windscreen 1	\$	480.00
Front windscreen moulding 1	\$	65.00
Dashboard 1	\$	980.00
LH dashboard air bag	\$	3,800.00
LH dashbaord air con vent	\$	120.00
LH windscreen pillar inner trim	\$	380.00
Air con blower box	\$	1,950.00
RH front seat belt	\$	480.00
	\$	25,756.00
Add 15%	\$	3,863.40
	\$	29,619.40
LH front door company sticker 1 S. nett	\$	25.00
Front windscreen sealant 1 S. nett	\$	80.00
Front windscreen inner rubber seal 1 S. nett	\$	28.00
Engine coolant 1 S. nett	\$	30.00
IU bracket 1 S. nett	\$	25.00
To remove and reinstall front windscreen and conduct water leak test	•	120.00
To remove and reinstall front windscreen and conduct water leak test	\$	120.00
To remove and check air con condenser, dryer, aluminium pipes, valves and reinstall		
components and vacuum and charge refrigerant R134a and check for leakage and		
full functionality	\$	120.00
Tun Tunctionanty	Ф	120.00
To remove and install dashboard and centre console, including instrument panel,		
centre info screen, radio, climate control module	\$	280.00
centre into screen, radio, chinate control module	Ф	200.00
To remove front damaged parts, to jack out front support panel, front body, and		
cut out damaged parts, to straighten out front chassis, to reweld, reshape and repair		
firewall, bonnet hinge panel, front fender and inner panel, head lamp inner panel,		
front support panel, front chassis member, to replace damaged parts and adjust		
body panel alignment	\$	1,400.00
body panel angilinent	Φ	1,400.00
To spray paint affected front and inner damaged portion inclusive of preparatory		
	\$	1,300.00
WOLKS and material	4	1,500.00



To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp

40.00

Towing charges

\$ 60.00

\$ 33,127.40

SS02218A0009 / S & H Motor Pte Ltd ENTRY DATE & TIME: 10/08/2021 17:34 (SGT) SUBMITTED BY: Wong Kee Nyuk VERSION: 1 (10/08/2021 17:34 (SGT))



# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

Please report <u>correctly</u> the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Authorised Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

# **ACCIDENT STATEMENT**

Date of Submission	10/08/2021 17:34 (SGT)
Date of Accident	06/08/2021 15:30 (SGT)
Exact Location of Accident	New Upper Changi Rd, Singapore
Additional Location Information	slip road of New Upper Changi Road towards Tanah Merah Kechil
	Road
Country/State of Loss	Singapore

DE TAILES OF	OWNVERNOLE
Vehicle Registration Number	GBC338L
INSURED/POLICYHOLDER	
Is company? Name Of Registered Owner Company Reg No Email Address Mobile Phone No Alternative Phone No	Yes Monli Curtain 5XXXX100L alvin1998@hotmail.sg (Phone) +65-94368766 (Home) +65-94368766
VEHICLE PARTICULARS	
Manufacturer	Touch

Manufacturer	Toyota
Model	Town Ace 1.5 DX M
Variant	-
Exact purpose for which vehicle was being used at time of	
accident	Employment
Are you claiming under your own insurance policy for repair to	
your vehicle?	Yes
Vehicle Category	Commercial vehicle
Transmission	Manual
CC	1495

Lonpac Insurance Bhd
Comprehensive
No
Z21VC05007458
1.

DRIVER

INSURANCE COMPANY

Name of Driver Tan Hong Thye



NIDIO No.	
NRIC No Date Of Birth	SXXXX882C
Date Of Birth Occupation	28/03/1955
Date Of Driving Pass	Indoor
Driving experience	22/07/1974
Gender	47 YEARS AND 1 MONTH
Mobile Number	Male
Alt. Phone Number	(Phone) +65-94368766
Email Address	1 1 1000 01 1 1
	alvin1998@hotmail.sg
	1 Joo Chiat Road #05-1003
Address complement	400004
Postcode	420001
Is the driver the policyholder?  If No, Relationship of the Driver with the Insured	No
	owner
Does Driver Own Other Vehicles?  Vehicle Registration Number of Other Vehicle Owned by Driver	No
vehicle Registration Number of Other Vehicle Owned by Driver	
Insurance Company of Other Vehicle Owned by Driver	
GENERAL INFORMATION OF THE ACCIDENT	
Turn of Accident	The same of the sa
Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry
OTHER INFORMATION	
Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	No 2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	. 1
Has the driver been approached by unknown person(s)	Contaction of
soliciting/offering accident claims assistance?	No
DETAILS OF POLICE ACTION	
Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	
CIRCUMSTANCES OF ACCIDENT	
refer attached report.	
ATTACHMENT(S)	
Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No
DETAILS OF OTHER	R VEHICLE PROPERTY 1
Vehicle Registration Number	VPO174M
Vehicle Registration Number Vehicle Manufacturer	YP2174M

Vehicle Registration Number	YP2174M
Vehicle Manufacturer	-
Vehicle Model	
Vehicle Variant	· · ·
Vehicle Colour	
Vehicle Category	Commercial vehicle
Name of Driver	
Contact Number	=
Address	pil *

On the Mouted drake as	of time I was tractiles along the	
	on the man more to make have the	at 17 was state for
checked the mygne	CK OX MEDITION OF	
a tr. mint and form t	h sly and. I proceeded to the	in into the anam
(C 10 110 C 274 A75		
soil when the traffic	was elever Ungerhandely, there	west a verta
arked illegally at the	Found from (double yellow Erre)	and I reallated
o the sear-of the June	s. After the collection, I writed	at the accessor
cene as where were n	o one in the long. I wered for a	round 20 minutes but
ic one camp que, the	nde, I am longing this insurance	cepart trapsher
onth the dorry is tar		
		The second secon
The second secon		
A STATE OF THE PARTY OF THE PAR		And the state of t
		And the second s
Annual Control of the		
		The second secon
the street and the st		
Declaration		
	are two in overy texting?	
WVe declare the foregoing particulars	Ste nuc aread a teolessa.	
文彩窗雕布是 Month Guntain		4
mande Questain	-2/3	
11000000	Driver's Signature (If driver is not the policyholder) / Date	Winessed by Reporting Centre
그 그 사람들은 아이들의 아이들의 사람들은 사람들이 되었다.		

# SKETCH PLAN

## IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the ladgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers law yers/faw firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
- (i) processing, handling and/or dealing with my claims including the suttlement of the claims and any necessary investigations relating to
- (ii) investigating the accident and/or my claims:
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me,
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers lawyers/law firms may/are permitted to collect use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers law firms), which may be sited outside of Singapore, for one or more of the above Purposes

-- Policyholder's Signature 7 Date &

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Frank Merch Sucht Ford