

Car-in

2/9/21

wip: 39011

Kiam /

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

AIG - Adrian

5 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 948 P

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Defunct</i>	1 S	2,832.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	1 S	650.00	+
3	FRONT BUMPER CLOSING ELEMENT - CENTER <i>new</i>	1 S	222.00	+
4	FRONT BUMPER ADAPTER - LH <i>new</i>	1 S	39.00	✓
5	FRONT BUMPER REINFORCEMENT COVER - LH ?	1 S	111.00	?
6	FRONT BUMPER CLOSING ELEMENT - LOWER <i>new</i>	1 S	210.00	?
7	FRONT AIR GUIDE GRILLE - LH <i>new</i>	1 S	434.00	✓
8	FRONT BUMPER AIR GUIDE - LH <i>new</i>	2 S	50.00	+
9	FRONT BUMPER REINFORCEMENT FOAM <i>new</i>	1 S	226.00	+
10	FRONT BUMPER REINFORCEMENT <i>new</i>	1 S	1,012.00	+
11	POP RIVET <i>new</i>	6 S	5.00	+
12	FRONT BUMPER SUPPORT ?	2 S	59.00	?
13	FRONT BUMPER BRACKET - LH <i>new</i>	1 S	54.00	+
14	FRONT BUMPER GUIDE SECTION - LH <i>new</i>	1 S	44.00	+
15	FRONT BUMPER TOP COVER <i>new</i>	1 S	126.00	+
16	FRONT PARKING AID SENSOR <i>new</i>	1	TBC	+
17	FRONT PARKING AID SENSOR SEAL <i>new</i>	4 S	14.00	+
18	HORN - LOW TONE ?	1 S	216.00	+
19	HORN BRACKET <i>new</i>	1 S	47.00	+
20	FRONT FENDER - LH <i>new</i>	1 S	1,468.00	✓
SUB TOTAL SPARE PARTS		:	\$ 7,819.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 948 P

S/N	PARTS DESCRIPTION	QTY		DAMAGED PARTS & PRICES	
				S/NETT	REMARKS
21	FRONT FENDER ATTACHMENT PARTS <i>Not in</i>	1	\$	42.00	X
22	FRONT FENDER BRACE - LH <i>Best</i>	1	\$	118.00	✓
23	FRONT FENDER BRACKET - LH UPPER ?	1	\$	44.00	?
24	FRONT HEADLIGHT MOUNTING - LH ?	1	\$	118.00	?
25	FRONT HEADLIGHT - LH <i>Cracked</i>	1	\$	8,624.00	✓
26	FRONT HEADLIGHT LIFT CYLINDER - LH <i>Cracked</i>	1	\$	198.00	✓
27	FRONT HEADLIGHT BRACKET - LH ?	1	\$	6.00	?
28	FRONT HEADLIGHT LIFT CYLINDER HOSE <i>Not in</i>	1	\$	182.00	X
29	FRONT FENDER TOP COVER - LH ?	1	\$	36.00	?
30	FRONT WHEEL HOUSING LINER - LH <i>Not in</i>	1	\$	275.00	+
31	FRONT WHEEL HOUSING LINER ATTACHEMENT PART <i>Not in</i>	1	\$	71.00	+
32	FRONT WHEEL SPOILER - LH <i>Not in</i>	1	\$	166.00	+
33	FRONT WHEEL STONE GUARD - LH <i>Not in</i>	1	\$	51.00	+
34	FRONT WINDOW CHROME TRIM STRIP - LH OUTER <i>Not in</i>	1	\$	200.00	+
35	FRONT WINDOW CHROME TRIM STRIP GUIDE - LH <i>Not in</i>	1	\$	257.00	+
36	SUNDRIES ?		\$	350.00	?
TOTAL SPARE PARTS		:	\$	18,557.00	
TOTAL LABOUR CHARGES		:	\$	7,944.00	
GRAND TOTAL		:	\$	26,501.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Resmied
Adrian Lj
06/09/21